

ArubaOS 7.4.1



Release Notes

Copyright Information

© 2015 Aruba Networks, Inc. All rights reserved. Aruba Networks®, Aruba Networks™ (stylized), People Move Networks Must Follow®, Mobile Edge Architecture®, RFProtect®, Green Island®, ClientMatch®, Aruba Central®, Aruba Mobility Management System™, ETips™, Virtual Intranet Access™, Aruba Instant™, ArubaOS™, xSec™, ServiceEdge™, Aruba ClearPass Access Management System™, AirMesh™, AirWave™, Aruba@Work™, Cloud WiFi™, Aruba Cloud™, Adaptive Radio Management™, Mobility-Defined Networks™, Meridian™ and ArubaCareSM are trademarks of Aruba Networks, Inc. registered in the United States and foreign countries. Aruba Networks, Inc. reserves the right to change, modify, transfer or otherwise revise this publication and the product specifications without notice.

Open Source Code

Certain Aruba products include Open Source software code developed by third parties, including software code subject to the GNU General Public License (GPL), GNU Lesser General Public License (LGPL), or other Open Source Licenses. Includes software from Litech Systems Design. The IF-MAP client library copyright 2011 Infoblox, Inc. All rights reserved. This product includes software developed by Lars Fenneberg et al. The Open Source code used can be found at this site:

http://www.arubanetworks.com/open_source

Legal Notice

The use of Aruba Networks, Inc. switching platforms and software, by all individuals or corporations, to terminate other vendors' VPN client devices constitutes complete acceptance of liability by that individual or corporation for this action and indemnifies, in full, Aruba Networks, Inc. from any and all legal actions that might be taken against it with respect to infringement of copyright on behalf of those vendors.

Warranty

This hardware product is protected by the standard Aruba warranty of one year parts/labor. For more information, refer to the ARUBACARE SERVICE AND SUPPORT TERMS AND CONDITIONS.

Altering this device (such as painting it) voids the warranty.

Contents	3
Release Overview	9
Supported Browsers	9
Related Documents	9
Contacting Support	10
What's New in this Release	11
New Features and Enhancements	11
Layer 2 and Layer 3 Features	11
GVRP Enhancements	11
OSPF Enhancements	11
Source IP Configuration for TACACS Server	11
Configuring Source IP	12
Support for Deleting a Switching-Profile	13
Verification of Switching-Profile Deletion	13
Enhancements to show running-config Command	13
Enhancements to Multicast Route Commands	13
Route Monitoring	14
Enhancements to Route Monitoring	14
IGMPv3 Snooping	14
Support for Static Address Resolution Protocol	15
Management Features	15
Troubleshooting Zero-Touch Provisioning	15
Enhancements to Traceoptions Command	16
Port Options	16
Filtering Options for OSPF and PIM	17
Enhancements to Reload Command	18

Support for Global and ACL-Based Packet Tracing	18
Enabling Global Packet Tracing	19
Sample Configuration	19
Enabling ACL-based Packet Tracing	19
Sample Configuration	19
Verifying Packet Tracing Configuration	19
Support for Factory-Reset on a Detached ArubaStack Member	20
SNMP Enhancements	20
Security Enhancements	20
Authentication Survivability	20
Important Points to Remember	21
Configuring Authentication Survivability	21
Sample Configuration	22
Verifying Authentication Survivability Configuration	22
Viewing Survived Authentication Entries	22
Clearing Cache Entries	22
Limitations	22
Support for Deleting Downloadable Roles	22
Security Update	23
Support for Port Bounce	23
Captive Portal Enhancements	23
Enhancements to Sticky MAC Configuration	23
Configuring Sticky MAC Action	24
Verifying Sticky MAC Configuration	24
Enhancements to ClearPass Policy Manager (CPPM) Server Authentication	24
Configure CPPM Server Credentials	24
Sample Configuration	24
Verifying Configuration	25
Enhancements to web-server Command	25
Session ACLs on RVI	25
Deny Inter-User Traffic	25

Enhancements to Netdestination Alias	26
QoS Enhancements	26
Support for QoS Trust on Tunneled Node Port	26
Branch Features	26
Support for IP NAT Outside	26
Support for Dynamic Domain Name Server Client	26
Support for Myonlineportal.net	26
Aruba VPN Tunnel	26
Distributed, L3 DHCP Scopes	26
NAT Pools	27
VPN Survivability	27
Default Route to VPN	27
Multiple Default Gateway Support	27
Access Point Integration Features	27
Configurable Rogue AP Containment	27
Dynamic Port Reconfiguration	28
Platform Features	28
Restoring Factory Default Settings on S1500	28
Configuring Mode Button on S1500	28
Verifying Mode Button Configuration	28
Platform Enhancements	28
WebUI Enhancements	28
Resolved Issues	29
AirWave/Activate	29
Base OS Security	29
Captive Portal	30
Configuration	30
Data Path Agent	31
DHCP	31

Generic Routing Encapsulation (GRE)	31
IPSec	32
Layer 2 Forwarding	32
Multicast	32
OSPF	33
RADIUS	33
Routing	34
Stacking	34
Switch-Datapath	35
Switch-Platform	35
WebUI	36
Known Issues and Limitations	37
Base OS Security	37
Central	38
Configuration	39
DHCP Snooping	39
Data Path Agent (DPA)	39
Dynamic ARP Inspection (DAI)	40
Generic Routing Encapsulation (GRE)	40
Interface	40
IPsec	40
IPv6	41
Layer 2 Forwarding	41
Multicast	41
OSPF	42
Port-Channel	42
QoS	42
Routing	43
Security	44

SNMP	45
Stacking	45
STP	45
Switch-Datapath	46
Switch-Platform	46
WebUI	48
Issues Under Investigation	48
Layer 2 Forwarding	48
Stacking	48
Upgrade Procedures	49
Important Points to Remember	49
Installing the FIPS Version of ArubaOS 7.4.1	49
Before Installing FIPS Software	49
Before You Upgrade	49
Save Your Configuration	50
Saving the Configuration in the WebUI	50
Saving the Configuration in the CLI	50
Upgrading to ArubaOS 7.4.1	50
Upgrading from the WebUI	50
Upgrading from the Command Line Interface	51
Upgrading from your USB using the LCD	51
Downgrading after an Upgrade	52
Before You Call Your Support Provider	53

ArubaOS 7.4.1 is a maintenance release that introduces new features, fixes to issues identified in the previous ArubaOS releases, and outstanding known issues and limitations in the current release. For details on all the features supported on Mobility Access Switch, see the [Related Documents](#) section.

This release note contains the following chapters:

- [What's New in this Release on page 11](#) describes the new features, fixes, known issues, and enhancements introduced in this release.
- [Upgrade Procedures on page 49](#) covers the procedures for upgrading a Mobility Access Switch to ArubaOS 7.4.1.

Supported Browsers

The following browsers are officially supported for use with the ArubaOS 7.4.1 WebUI:

- Microsoft Internet Explorer 9.x and 10.x on Windows XP, Windows Vista, Windows 7, and Windows 8
- Mozilla Firefox 17 or higher on Windows XP, Windows Vista, Windows 7, and MacOS
- Apple Safari 5.1.7 or higher on MacOS

Related Documents

The following documents are part of the complete documentation suite for the Aruba Mobility Access Switch:

- *ArubaOS 7.4 User Guide*
- *ArubaOS 7.4 Command Line Reference Guide*
- *ArubaOS 7.4 Quick Start Guide*
- *Aruba S3500 Series Mobility Access Switch Installation Guide*
- *Aruba S2500 Series Mobility Access Switch Installation Guide*
- *Aruba S1500 Series Mobility Access Switch Installation Guide*

Contacting Support

Table 1: *Contact Information*

Website Support	
Main Site	arubanetworks.com
Support Site	support.arubanetworks.com
Airheads Social Forums and Knowledge Base	community.arubanetworks.com
North American Telephone	1-800-943-4526 (Toll Free) 1-408-754-1200
International Telephone	http://www.arubanetworks.com/support-services/support-program/contact-support
Software Licensing Site	https://licensing.arubanetworks.com/
End-of-Support Information	http://www.arubanetworks.com/support-services/end-of-life-products/
Security Incident Response Team (SIRT)	http://www.arubanetworks.com/support-services/security-bulletins/
Support Email Addresses	
Americas, EMEA, and APAC	support@arubanetworks.com
Security Incident Response Team (SIRT)	sirt@arubanetworks.com

New Features and Enhancements

New features in the following categories are introduced in ArubaOS 7.4:

- [Layer 2 and Layer 3 Features on page 11](#)
- [Management Features on page 15](#)
- [Security Enhancements on page 20](#)
- [QoS Enhancements on page 26](#)
- [Branch Features on page 26](#)
- [Access Point Integration Features on page 27](#)
- [Platform Features on page 28](#)
- [WebUI Enhancements](#)

Layer 2 and Layer 3 Features

This release of ArubaOS provides support for the following Layer 2 and Layer 3 features and enhancements:

GVRP Enhancements

Starting from ArubaOS 7.4.1, the following warning message is displayed on the Mobility Access Switch if you apply the GVRP profile on an interface without enabling global GVRP:

Warning: GVRP not enabled globally.

The sample command output with the warning message is as follows:

```
(host) (gigabitethernet "0/0/1") #switching-profile vlan10
(host) (gigabitethernet "0/0/1") #gvrp-profile vlan10
```

Warning: GVRP not enabled globally.

OSPF Enhancements

Starting from ArubaOS 7.4.1, Mobility Access Switch introduces the **show ip ospf interface brief** command to display OSPF details such as Interface, Instance, Area, IP/MASK, Cost, State, and Neighbors in a brief tabular format.

The following sample displays the output of the **show ip ospf interface brief** command in a tabular format:

```
(host) # show ip ospf interface brief
Brief OSPF Interface Information
-----
Interface Instance Area IP Address/Mask Cost State Neighbors F/C
-----
vlan201 0 0.0.0.0 69.1.1.1/255.255.255.0 1 DOWN 0/0
vlan202 0 0.0.0.1 79.11.1.1/255.255.255.0 1 DOWN 0/0
```



In the **show** command output, the **Neighbors F/C** column represents fully adjacent neighbors and the total number of adjacent neighbors, respectively.

Source IP Configuration for TACACS Server

Starting from ArubaOS 7.4.1, the Mobility Access Switch introduces the **source-interface** command at the global and profile levels for the TACACS server. This command allows you to select a specific source interface IP address for the outgoing TACACS packets.

Configuring Source IP

The global source interface command is used to specify the source interface for all TACACS server request packets. If the source interface IP address is configured at the profile level, it takes precedence over the global source interface IP address.

The syntax for the global **source-interface** command is as follows:

```
(host) (config) #ip tacacs source-interface {loopback | vlan <id> [secondary <ip>]}
```

The following is a sample global **source-interface** command:

```
(host) (config) #ip tacacs source-interface vlan 55
```

The syntax for the profile-level **source-interface** command is as follows:

```
(host) (config) # aaa authentication-server tacacs <tacacs_server_name>
(host) (TACACS Server "<tacacs_server_name>") #source-interface {loopback | vlan <id>
[secondary <ip>]}
```

Some sample profile-level **source-interface** commands are as follows:

```
(host) (config) #aaa authentication-server tacacs tac1
(host) (TACACS Server "tac1") #source-interface loopback
(host) (config) #aaa authentication-server tacacs tac2
(host) (TACACS Server "tac2") #source-interface vlan 55
```

The following table describes the parameters for the **source-interface** command:

Table 2: Parameters for the **source-interface** command

Parameter	Description
loopback	Assigns the switch IP as the source IP.
vlan <id>	Assigns the IP address of the specified VLAN interface as the source IP.
secondary <ip>	Assigns a secondary source IP address in A.B.C.D format. This parameter is optional.

The following sample command configures the secondary IP address of VLAN 10 as the source interface IP address for all TACACS server request packets, provided there is no profile-level configuration:

```
(host) (config) #ip tacacs source-interface vlan 10 secondary 10.1.1.1
```

The following sample command configures the secondary IP address of VLAN 20 as the source interface IP address for a specific TACACS server:

```
(host) (config) #aaa authentication-server tacacs tac1
(host) (TACACS Server "tac1") #source-interface vlan 20 secondary 10.1.1.2
```

The following sample displays the output of the **show ip tacacs source-interface** command for the global and profile-level configurations mentioned here:

- The global source-interface is configured as vlan 55.
- The profile-level source-interfaces are configured as loopback and vlan 55 for two server profiles.

```
(host) (config) #show ip tacacs source-interface
Global TACACS source interface:
vlan: 55
ip: 55.0.0.2
loopback: disabled
Per-server client source IP addresses:
Server "tac1": loopback enabled
Server "tac2": vlan 55, IP 55.0.0.2
```

Support for Deleting a Switching-Profile

Starting from ArubaOS 7.4.1, the Mobility Access Switch introduces the **no switching-profile** command inside a tunnel to remove any switching-profile applied to the tunnel and point the tunnel back to the default switching-profile.

The following sample command deletes the switching-profile from the interface tunnel 50:

```
(host) (config) #interface tunnel ethernet 50
(host) (Tunnel "50") #no switching-profile
```

Verification of Switching-Profile Deletion

Execute the following **show interface tunnel** command to verify if any switching-profile applied to the tunnel is removed:

```
(host) (Tunnel "50") #show interface tunnel 50

tunnel 50 is administratively Up, Line protocol is Down
Description: GRE Interface
Source unconfigured
Destination unconfigured
Tunnel mtu is set to 1100
Tunnel keepalive is disabled
Tunnel is an L2 GRE Tunnel
Protocol number 0
Tunnel is Trusted
Inter Tunnel Flooding is enabled
Switching-profile "default"
GRE Tunnel is up and running since: 00 00:00:00
```

The **show interface tunnel** command output displays the switching-profile as **default** when no switching-profile is applied to the interface tunnel.

Enhancements to show running-config Command

Starting from ArubaOS 7.4.0.2, the probe-profile protocol information (default value is ICMP) is displayed in the output of the **show running-config** command. The following sample displays the probe-profile protocol in the output of the **show running-config** command:

```
(host) (config) #show running-config | include icmp
Building Configuration...
netsservice svc-icmp 1
ip access-list stateless icmp-acl-stateless
any any svc-icmp permit
any any svc-icmp permit
access-list stateless icmp-acl-stateless
protocol icmp
```

Enhancements to Multicast Route Commands

Starting from ArubaOS 7.4.0.2, the counters for multicast route entries are included in the output of the following show commands:

- show ip pim mroute
- show ip pim mroute detail
- show ip pim-ssm mroute
- show ip pim-ssm mroute detail

The following sample displays the multicast counter values in the output of **show ip pim mroute** command:

```
(host) #show ip pim mroute
IP Multicast Route Table
Flags: D - Dense, S - Sparse, s - SSM, C - Connected Receiver,
```

J - Join SPT, R - RP-bit set, T - SPT bit set
F - Register Flag, N - Null Register, A - Assert Winner

Total (*,G) Entries : 0

Total (S,G) Entries : 0

Total (*,G) Entries is the number of multicast routes to a specific group from any source.

Total (S,G) Entries is the number of multicast routes from a specific source to a specific group.

Route Monitoring

Starting from ArubaOS 7.4, Mobility Access Switch provides support for Route Monitoring. Route Monitoring enables the Mobility Access Switch to monitor the L3 uplink status using the ping probe. The ping probe destined to a server IP address is sent on the uplink interface which is under monitoring. Based on the status of the ping reply, the probe status of the interface is updated to up or down. When the probe status of the interface is down, the Mobility Access Switch removes the interface host and network routes from the routing table. When the probe status of the interface is up, interface host and network routes are added back.



By default, Route Monitoring is disabled on the Mobility Access Switch.

For more information on configuring Route Monitoring, see *ArubaOS 7.4 User Guide*.

Enhancements to Route Monitoring

Starting from ArubaOS 7.4.0.3, the output of the **show probe** command displays a new column, **Flags**. The **Flags** column indicates the causes due to which the probe status of the interface is down. The cause can be one of the following:

- IP is your own-ip
- Protocol is down for the interface
- IP not assigned for the interface
- MAC is not resolved for the route next-hop
- Route is not present for the probe destination
- URL is not resolved



If the URL is not resolved, the probe status of the interface remains as Up to ensure that the routes remain in the routing table to reach the DNS server. However, the **Sent** and **Received** columns display **N/A** to indicate that no packets are forwarded.

The following sample displays the output of the **show probe** command:

```
(host) #show probe
IPV4 PROBE Table
-----
Vlan      Server                Protocol  Port   Probe-State  Sent  Received  Flags
-----
vlan1     10.16.44.110          ICMP     N/A    Own-IP       N/A   N/A       IP is your own-ip
vlan1     10.16.52.8            ICMP     N/A    Up           2     1         N/A
vlan1     www.google.com        ICMP     N/A    Up           1     0         N/A
vlan50    10.16.52.8            ICMP     N/A    Down         N/A   N/A       Protocol is down for the
interface
Total Probe host entries: 4
```

IGMPv3 Snooping

The Mobility Access Switch provides support for IGMPv3 snooping starting from ArubaOS 7.4. IGMPv3 Snooping is used to snoop the membership reports that have group records of different types. These group

records specify the source specific Multicast (SSM) traffic for a particular group.

IGMP Snooping is configured as a profile under `vlan-profile` and is attached to a VLAN. By default, v3 snooping is disabled and v2 snooping is enabled in an `igmp-snooping` profile. A new configuration command is introduced to enable v3 snooping explicitly.

For more information on IGMPv3 Snooping, see *ArubaOS 7.4 User Guide*.

Support for Static Address Resolution Protocol

Starting from ArubaOS 7.4, you can add a static Address Resolution Protocol entry on the Mobility Access Switch. You can configure a static ARP entry using the CLI. For more information, see *ArubaOS 7.4 User Guide*.

Management Features

This release of ArubaOS provides support for the following Management features:

Troubleshooting Zero-Touch Provisioning

Starting from ArubaOS 7.4.1, Mobility Access Switch introduces the **show ztp-boot-info** command to help troubleshoot any Zero Touch Provisioning (ZTP) issues.

For more information about ZTP, see *ArubaOS 7.4 User Guide*.

The output of the **show ztp-boot-info** command displays the status of various methods of provisioning a Mobility Access Switch. The output details include TFTP configuration download status, DHCP AMP discovery status, Activate AMP discovery status in addition to DHCP options received.

The following sample output displays the details of the TFTP method of provisioning:

```
(host) (config) #show ztp-boot-info
Zero Touch Provisioning Method: TFTP
Time of Provisioning           : Jun/18/2015 06:43:07
TFTP Config Download          : Successful
DHCP AMP Discovery             : N/A
Activate AMP Discovery         : N/A
DHCP Options Received
-----
Option No. Option Name  Value
-----
3          Router        192.168.1.2
6          DNS Server    10.13.6.110
43         VSA
60         Vendor
67         Bootfile     AW0000161.cfg
150        TFTP Server  10.16.59.60
```

The following sample output displays the details of provisioning through Activate:

```
(host) #show ztp-boot-info
Zero Touch Provisioning Method: Activate
Time of Provisioning           : N/A
TFTP Config Download          : Failed
DHCP AMP Discovery             : Failed
Activate AMP Discovery         : Failed
DHCP/Activate provisioning aborted.
DHCP Options Received
-----
Option No. Option Name  Value
-----
3          Router        192.168.1.2
6          DNS Server    10.13.6.110
43         VSA
60         Vendor
```

The following table describes the output parameters for the **show-ztp-boot-info** command:

Table 3: Description for Output Parameters of **show-ztp-boot-info** Command

Parameter	Description
Zero Touch Provisioning Method	Displays TFTP or Activate . NOTE: Whenever ZTP fails, this still shows Activate as the provisioning method as the Mobility Access Switch keeps polling Activate in the background as long as it is in factory default.
Time of Provisioning	Displays the Timestamp of provisioning in Date and Time format. NOTE: This field displays N/A if not provisioned.
TFTP Config Download	Displays Successful or Failed . NOTE: If TFTP is the chosen ZTP method, it is the first method to attempt provisioning, and the output displays Successful ; otherwise, the output displays Failed .
DHCP AMP Discovery	Displays Successful if the AMP parameters were discovered through DHCP option 43. NOTE: If TFTP is the chosen method of provisioning, this is not applicable.
Activate AMP Discovery	Displays one of the following: <ul style="list-style-type: none"> • Successful, if the AMP parameters are received through Activate. • N/A, if the method is not attempted. • Failed, if provisioning fails.
DHCP Options Received	Displays the various DHCP options received with the name and value in tabular format.

Enhancements to Traceoptions Command

Port Options

Starting from ArubaOS 7.4.1, the **port** command under traceoptions allows you to specify the actual interface number or the port-channel instead of specifying the index number of the port. The following two options are introduced under the **port** command:

- **gigabitethernet**—Specify the actual interface number
- **port-channel**—Specify the port-channel ID

The sample **port** configuration commands are as follows:

```
(host) (traceoptions) #mstp port gigabitethernet 0/0/6
(host) (traceoptions) #mstp port port-channel 1
```

The sample **show traceoptions** command with the port name displayed as the actual interface number is provided here:

```
(host) (traceoptions) #show traceoptions
traceoptions (N/A)
-----
Parameter                               Value
-----
Layer2 Forwarding trace flags
Layer2 Forwarding trace level           debugging
Layer2 Forwarding trace file size (Mb)  10
MSTP trace flags
```

```

MSTP trace port gigabitethernet      0/0/6
MSTP trace port port-channel          N/A
Interface manager trace flags         infrastructure configuration ethernet vlan port-
channel tunnel loopback mgmt system-information
Interface manager trace level         debug
Chassis manager trace flags           fru poe-configuration interface association debug
LLDP trace flags
dhcp_snoop trace flags
igmp-snooping trace flags
pim sparse mode trace flags
ospf trace flags
routing trace flags
igmp trace flags
vrrp trace flags
ddns trace flags
stack-manager trace flags             primary-election route system webui configuration
Stack-manager trace level             informational
rmon trace flags
rmon trace level                      errors
rmon trace file size (Mb)             10
(Host) (traceoptions) #
(Host) (traceoptions) # show running-config | include mstp
Building Configuration...
mstp port gigabitethernet "0/0/6"
interface-profile mstp-profile "default"
mode mstp
mstp

```

Filtering Options for OSPF and PIM

Starting from ArubaOS 7.4.1, the **show traceoptions** command is enhanced to filter OSPF and PIM traces by interface ID.

Users can configure OSPF VLAN ID and Tunnel ID as filters using the following CLI commands:

```

(host) (traceoptions) #ospf vlanid <ID>
(host) (traceoptions) #ospf tunlid <ID>

```

Similarly, users can configure PIM VLAN ID and Tunnel ID as filters using the following CLI commands:

```

(host) (traceoptions) #pim vlanid <ID>
(host) (traceoptions) #pim tunlid <ID>

```

The following is a sample OSPF trace VLAN ID configuration command:

```

(host) (traceoptions) #ospf vlanid 800

```

The sample output of the **show traceoptions** command for the preceding OSPF VLAN configuration is as follows:

```

(host) (traceoptions) #show traceoptions
traceoptions (N/A)
-----
Parameter                                Value
-----
Layer2 Forwarding trace flags
Layer2 Forwarding trace level             debugging
Layer2 Forwarding trace file size (Mb)    10
MSTP trace flags
MSTP trace port gigabitethernet          N/A
MSTP trace port port-channel              N/A
Interface manager trace flags             infrastructure configuration ethernet vlan port-
channel tunnel loopback mgmt system-information
Interface manager trace level             error
Chassis manager trace flags               fru poe-configuration interface association debug
LLDP trace flags

```

```

dhcp_snoop trace flags
igmp-snooping trace flags
pim sparse mode trace flags          all
pim sparse mode trace by vlanid      0
pim sparse mode trace by tunnel id   0
ospf trace flags                      all
OSPF trace by vlanid                800
ospf trace by tunnel id              0
routing trace flags
igmp trace flags
vrrp trace flags
ddns trace flags
stack-manager trace flags             primary-election route system webui configuration
Stack-manager trace level            informational
rmon trace flags
rmon trace level                      errors
rmon trace file size (Mb)            10

```



Without OSPF or PIM trace configuration, no filtering is done by VLAN ID and Tunnel ID and the output of **show traceoptions** command displays 0, by default.

Enhancements to Reload Command

The **reload** command is enhanced with more options such as **reload in** and **reload at** to reload a switch or stack member in/at a specific time and/or date.

The following table provides description for the available reload options:

Table 4: Parameters for the **reload** Command

Parameter	Description	Range
in <minutes>	Reloads the stack or switch after the specified time.	0-60
at <hours, minutes, month, date>	Reloads the switch or stack at a specific time and date in the format: <hours, minutes, month, date>.	0-23, 0-60, 1-12, 1-31
cancel	Cancels the scheduled reload from the switch	
<member> in <minutes>	Reloads a stack member after the specified time.	0-60 minutes
<member> at <hours, minutes, month, date>	Reloads a stack member at a specific time and date.	0-23, 0-60, 1-12, 1-31

The following command reloads the switch after 60 minutes:

```
(host) #reload in 60
```

The following command reloads the switch at a specific time and date:

```
(host) #reload at 1 50 7 12
```

Support for Global and ACL-Based Packet Tracing

Starting from ArubaOS 7.4.1, Mobility Access Switch introduces the following CLI commands to enable global and ACL-based packet tracing:

- pkt-trace-global enable
- pkt-trace acl <ACL-name> enable

Enabling Global Packet Tracing

Execute the following CLI command to enable global packet tracing:

```
(host) # pkt-trace-global enable
```

Execute the following CLI command to disable global packet tracing:

```
(host) # pkt-trace-global disable
```

The following table describes the parameters of the **pkt-trace-global enable** command:

Table 5: Parameters for the **pkt-trace-global enable** command

Parameter	Description
trace	Configures datapath trace options.
trace-hex-mask <tmask>	Configures datapath trace mask in Hex format.

Sample Configuration

The following sample **pkt-trace global** command configures trace mask for ACL functionality:

```
(host) # pkt-trace-global enable trace-hex-mask 0 trace acl-processing
```

Enabling ACL-based Packet Tracing

Execute the following CLI command to enable packet tracing for an ACL entry:

```
(host) # pkt-trace acl <ACL-name> enable
```

Execute the following CLI command to disable packet tracing for an ACL entry:

```
(host) # pkt-trace acl <ACL-name> disable
```

The following table describes the parameters of the **pkt-trace acl enable** command:

Table 6: Parameters for the **pkt-trace acl enable** command

Parameter	Description
log	Writes packet trace data into log file.
trace	Configures datapath trace options.
trace-hex-mask <tmask>	Configures datapath trace mask in Hex format.

Sample Configuration

The following sample **pkt-trace acl** command writes packet trace data into log file for the stated ACL bug:

```
(host) #pkt-trace acl acl-bug-58651 enable log trace acl-processing
```

Verifying Packet Tracing Configuration

The following **show** command helps verify the packet tracing configuration:

```
(host) #show datapath debug trace-buffer
Datapath Trace Buffer Entries:
MacAddr(   bb) 0x0      0x0      0x0      0x0      0xb86a1
0x6ac00000
MacAddr(   bb) 0x0      0x0      0x0      0x0      0xb86a1
```

```

0x6ac00000
MacAddr (   bb) 0x0      0x0      0x0      0x0      0xb86a1
0x6ac00000
CPDNSok (   4f) 0x0      0x1      0xa1045a2 0x37     0x1f
0x0
...

```



The **show** command output may not completely imply that the packet tracing configuration is set. Enabling packet tracing might impact the throughput of the system.

Support for Factory-Reset on a Detached ArubaStack Member

Starting from ArubaOS 7.4.0.3, you can reset a detached ArubaStack member that boots up as a line card to its factory defaults. This allows you to reset the password on the Mobility Access Switch if the login credentials are lost.

To reset a line card to its factory-defaults:

1. Connect a local console to the serial port on the Mobility Access Switch.
2. From the console, login to the Mobility Access Switch using the username, **password** and the password, **forgetme!**.
3. Execute the following commands:

```
(LC-1) #restore factory_default stacking
(LC-1) #reload
```

SNMP Enhancements

This release of ArubaOS provides support for the following SNMP enhancements:

- Starting from ArubaOS 7.4.0.3, the slot details of the ArubaStack are included in the power supply missing trap.
- Starting from ArubaOS 7.4.0.2, the following Aruba Enterprise traps for linkup/linkdown status are introduced in the Mobility Access Switch:
 - **wlslifLinkDownTrap**—This trap is sent when the operational state of a link transitions to down state from any other state (indicated by **ifOperStatus** object in the trap).
 - **wlslifLinkUpTrap**—This trap is sent when the operational state of a link transitions to up state from any other state (indicated by **ifOperStatus** object in the trap).

Security Enhancements

This release of ArubaOS provides support for the following Security Enhancements:

Authentication Survivability

The authentication survivability feature supports a survivable authentication framework against the remote link failure when working with the CPPM authentication servers. When enabled, this feature allows the Mobility Access Switches to authenticate the previously connected clients against the cached credentials if the connection to the authentication server is temporarily lost.

Starting from ArubaOS 7.4.1, Mobility Access Switch supports the following authentication methods with Authentication Survivability:

- 802.1X clients with Termination disabled/enabled: EAP-TLS with CPPM as RADIUS server.
- MAC-Based Authentication clients: PAP method. CPPM server is not mandatory in this case.



This release of ArubaOS supports only EAP-TLS standard for Authentication Survivability.

When the authentication survivability feature is enabled, the following authentication process is used:

1. The wired client connects to a Mobility Access Switch and authenticates to the external authentication server. The external authentication server can be CPPM.
2. Upon successful authentication, the Mobility Access Switch caches the authentication credentials of the connected users for the configured duration. The cache expiry duration for authentication survivability can be set within the range of 1-72 hours, with 24 hours being the default cache timeout duration.
3. If the client roams or tries to reconnect to the Mobility Access Switch and the remote link fails due to the unavailability of the authentication server, the Mobility Access Switch uses the cached credentials in the internal authentication server to authenticate the user. However, if the user tries to reconnect after the cache expiry, the authentication fails.
4. When the authentication server is available and if the client tries to reconnect, the Mobility Access Switch detects the availability of server and allows the client to authenticate to the server. Upon successful authentication, the Mobility Access Switch cache details are refreshed.

The following attributes are supported from CPPM server along with the caching credentials:

- PW_USER_NAME
- PW_SESSION_TIMEOUT
- MS_TUNNEL_TYPE
- MS_TUNNEL_MEDIUM_TYPE
- MS_TUNNEL_PRIVATE_GROUP_ID
- ARUBA_ROLE
- ARUBA_VLAN
- ARUBA_CPPM_ROLE (Downloadable Role)
- ARUBA_ADMIN_ROLE

Important Points to Remember

- Any client connected through CPPM and authenticated through Mobility Access Switch remains authenticated with the Mobility Access Switch even if the client is removed from the CPPM server during the CPPM downtime.
- For EAP-TLS authentication, ensure that the CPPM 6.5.1.7 or later version is used for authentication.
- The cached credentials of a client will be deleted, if it fails the authentication via CPPM server. The credentials will be cached again if the subsequent authentication is successful.
- When the role download fails for a user after successful authentication from CPPM, the user will remain in initial or a previously known role even though the cache table cached the name of the role that failed to download, The role is not applied to the user when the CPPM server is down. The clients must do a fresh authentication with the cached credentials.
- When the CPPM server is unreachable, the user gets authenticated with the cached credentials only if all the following entries match the cached entries:
 - mac address
 - username
 - auth-type (EAP-TLS or PAP)

Configuring Authentication Survivability

You can enable authentication survivability on the Mobility Access Switch using the following CLI command:

```
(host) (config) #aaa auth-survivability enable
```

Execute the following command to set the duration after which the authenticated credentials in the cache must expire.

```
(host) (config) #aaa auth-survivability cache-lifetime <1-72>
```

Specify a value in hours for Cache timeout. The allowed range is 1 to 72 hours and the default value is 24 hours.

Execute the following command to specify a server certificate which will be used by the survival server to terminate EAP-TLS for 802.1X authentication.

```
(host) (config) #aaa auth-survivability server-cert ?
<server-cert-name>      Name of the Server Certificate
```

Sample Configuration

```
(host) (config) #aaa auth-survivability enable
(host) (config) #aaa auth-survivability cache-lifetime 25
```

Verifying Authentication Survivability Configuration

Execute the following command to verify the Authentication Survivability configuration on the Mobility Access Switch:

```
(host) (config) #show aaa auth-survivability
Auth-Survivability: Enabled (Running)
Survival-Server Server-Cert: server-crt
Survival-Server Cache lifetime: 72 hours
```

Viewing Survived Authentication Entries

To view the cached entries on Mobility Access Switch, use the following command:

```
(host) #show aaa auth-survivability-cache
Auth-Survivability Cached Data
-----
MAC                User Name          Authenticated By  Authenticated On  Attributes          AuthType
-----
00:00:00:01:01:01  00:00:00:01:01:01  cppm1            2015-06-11 08:02  CPPM Role(auth_surv-3167-2)  PAP
```

Clearing Cache Entries

To clear the cache entries manually, use the following commands:

```
(host) (config) #clear aaa auth-survivability-cache mac <mac address of client>
(host) (config) #clear aaa auth-survivability-cache all
```

Limitations

- 802.1X reauthentication timer value should be less than the dead interval time.

Support for Deleting Downloadable Roles

Starting from ArubaOS 7.4.1, Mobility Access Switch provides support for deleting downloadable roles from the CPPM server if the following conditions are met:

- No user references it
- It is in **Complete** or **Incomplete** state

Execute the following CLI command for deleting a role downloaded from the CPPM server:

```
(host) #downloadable-role-delete <role>
```



The following error message is displayed if you try to delete a role that is not downloaded from CPPM or a non-existing role:

```
Invalid role <role-name>
```

The following sample CLI command deletes the abc_profile-3023-8 user role:

```
(host) #downloadable-role-delete abc_profile-3023-8
```

Security Update

Starting from ArubaOS 7.4.1, the BASH access is disabled on Mobility Access Switch for security reasons.

Support for Port Bounce

Starting from ArubaOS 7.4.0.3, Mobility Access Switch provides support for the port bounce feature which enables a client to re-initiate a DHCP request when there is a VLAN change. This is achieved when a RADIUS server such as CPPM sends Disconnect-Request with a Vendor Specific Attribute (VSA 40) to the Mobility Access Switch to trigger an interface shut down for a specified period. This allows the device to re-initiate a DHCP request for obtaining an IP address in the changed subnet.

The Disconnect-Request must include the following information:

- Calling Station-Id—MAC address of the user
- VSA—40
- Integer—0-60

VSA 40 represents Aruba-Port-Bounce-Host. The integer value indicates the time in seconds for which the Mobility Access Switch must shut the interface down. If the integer value received is 0 or a number greater than 60, the Mobility Access Switch does not shut the interface down.



During a port bounce, the client connected to the interface is removed from the user table and is added back after the port is up.

Execute the following command to view the security logs during and after a port bounce:

```
(host) #show log security all | include Port
```

The following sample shows the output during a port bounce:

```
Press 'q' to abort.
Apr 29 06:06:19 :124004: <DEBUG> |authmgr| Port Bounce Link Down flag set. Port =
gigabitethernet0/0/6.
Apr 29 06:06:19 :124004: <DEBUG> |authmgr| LIF_OPER_STATE_UP. Port = gigabitethernet0/0/6.
Apr 29 06:06:20 :124004: <DEBUG> |authmgr| Port will come up within 60 secs. link =
0x106ea2ac.
```

The following sample shows the output after a port bounce:

```
Press 'q' to abort.
Apr 29 06:06:19 :124004: <DEBUG> |authmgr| Port Bounce Link Down flag set. Port =
gigabitethernet0/0/6.
Apr 29 06:06:19 :124004: <DEBUG> |authmgr| LIF_OPER_STATE_UP. Port = gigabitethernet0/0/6.
Apr 29 06:06:20 :124004: <DEBUG> |authmgr| Port will come up within 60 secs. link =
0x106ea2ac.
Apr 29 06:07:20 :124004: <DEBUG> |authmgr| Port Bounce Link DOWN flag reset. Port =
gigabitethernet0/0/6.
```

Captive Portal Enhancements

Starting from ArubaOS 7.4.0.3, the **Authorization Required** page appearing before the actual Captive Portal login page is removed from the Mobility Access Switch.

Enhancements to Sticky MAC Configuration

Starting from ArubaOS 7.4.0.2, the Mobility Access Switch allows you to configure the Sticky MAC feature with an action to take when a Sticky MAC violation occurs. The allowed actions are:

- Drop—Drops any new MAC addresses trying to connect to the interface. This is the default option.
- Shutdown—Shuts down the port on which the sticky MAC violation occurs. You can also optionally set an auto-recovery time between 0-65535 seconds for the interface to recover.

Configuring Sticky MAC Action

To enable and configure a Sticky MAC action, execute the following command:

```
(host) (config) #interface-profile port-security-profile <profile-name>
(host) (Port security profile "<profile-name>") #sticky-mac action [drop | shutdown auto-recovery-time <1-65535>]
```

Sample Configuration

```
(host) (config) #interface-profile port-security-profile sticky
(host) (Port security profile "sticky") #sticky-mac action shutdown auto-recovery-time 10
```

Verifying Sticky MAC Configuration

Execute the following command to verify the Sticky MAC configuration:

```
(host) #show interface-profile port-security-profile <profile-name>
```

The following command verifies the sample configuration:

```
(host) #show interface-profile port-security-profile sticky
Port security profile "sticky"
```

```
-----
Parameter                                         Value
-----
IPV6 RA Guard Action                             N/A
IPV6 RA Guard Auto Recovery Time                 N/A
MAC Limit                                         N/A
MAC Limit Action                                 N/A
MAC Limit Auto Recovery Time                     N/A
Sticky MAC                                       Enabled
Sticky MAC Action                                   Shutdown

Sticky MAC Auto Recovery Time                   10 Seconds
Trust DHCP                                       No
Port Loop Protect                                N/A
Port Loop Protect Auto Recovery Time             N/A
IP Source Guard                                  N/A
Dynamic Arp Inspection                            N/A
```

Enhancements to ClearPass Policy Manager (CPPM) Server Authentication

To download roles from the CPPM server, the Mobility Access Switch requires to provide the CPPM server admin credentials starting from CPPM 6.4.3. To achieve this, a new CLI command is introduced in ArubaOS 7.4.0.2. Using this command,

you can configure the CPPM admin username/password, under **authentication-server** definition on the Mobility Access Switch.

Configure CPPM Server Credentials

Use the following command to configure CPPM Username/password:

```
(host) (config) #aaa authentication-server radius <server-name>
(host) (RADIUS Server "<server-name>") #cppm username <username> password <password>
```

Sample Configuration

```
(host) (config) #aaa authentication-server radius cppm1
(host) (RADIUS Server "cppm1") #host 1.1.1.1
(host) (RADIUS Server "cppm1") #key key123
(host) (RADIUS Server "cppm1") #cppm username admin password password123
(host) (RADIUS Server "cppm1") #exit
```

Verifying Configuration

The following show command displays the CPPM server credentials configured on the Mobility Access Switch:

```
(host) (config) #show aaa authentication-server radius cppm1
RADIUS Server "cppm1" (N/A)
-----
Parameter                               Value
-----
Host                                     1.1.1.1
Key                                       *****
CPPM credentials                       admin/*****
Auth Port                                1812
Acct Port                                 1813
Retransmits                              3
Timeout                                  5 sec
NAS ID                                    N/A
NAS IP                                    N/A
Source intf                              N/A
Use MD5                                   Disabled
Use IP address for calling station ID     Disabled
Mode                                       Enabled
```

Enhancements to web-server Command

As part of [CVE-2014-3566](#) security vulnerabilities and exposures, **SSLv3** transport layer security is disabled from ArubaOS 7.4.0.1.



Clients exclusively using SSLv3 will fail to access Captive Portal or Mobility Access Switch WebUI. It is recommended to use TLSv1, TLSv1.1, or TLSv1.2 transport layer security.

To address this, the following changes are introduced under the **web-server ssl-protocol** command.

Parameter	Description	Range	Default
ssl-protocol tlsv1 tlsv1.1 tlsv1.2	Specifies the Secure Sockets Layer (SSL) or Transport Layer Security (TLS) protocol version used for securing communication with the web server: <ul style="list-style-type: none">• TLS v1• TLS v1.1• TLS v1.2	—	tlsv1 tlsv1.1 tlsv1.2

Session ACLs on RVI

Starting from ArubaOS 7.4, you can apply session ACLs on a routed VLAN interface (RVI) of the Mobility Access Switch. For more information on configuring session ACLs on RVI, see *ArubaOS 7.4 User Guide*.

Deny Inter-User Traffic

Starting from ArubaOS 7.4, Mobility Access Switch provides support for Deny Inter-user Traffic. Deny Inter-user Traffic feature enables Mobility Access Switches to block the communication between users with the same role. For example, an organization can block communication between any two guest users. If the role has voip-profile configured, then the traffic across the VoIP users is also denied.



The inter-user traffic denial happens only within an ArubaStack and does not span across multiple Mobility Access Switches or ArubaStack.

By default this feature is disabled. You can configure Deny Inter-user Traffic for a maximum of seven user-roles (including CPPM downloaded roles) on a per user-role basis. For more information on configuring Deny Inter-User Traffic, see *ArubaOS 7.4 User Guide*.

Enhancements to Netdestination Alias

Starting from ArubaOS 7.4, a new netdestination alias, **localip** is introduced in the Mobility Access Switch. This is a system-defined alias which can be used as a destination alias for all the local IP addresses defined in the Mobility Access Switch.

QoS Enhancements

This release of ArubaOS provides support for the following QoS Enhancements:

Support for QoS Trust on Tunneled Node Port

Starting from ArubaOS 7.4.0.3, if **qos-trust** is enabled on a Tunneled Node port, the QoS markings (DSCP/dot1p) of the incoming packet are copied to the outer GRE header packet as well. This enables appropriate QoS treatment along the tunnel path.

Branch Features

This release of ArubaOS provides support for the following portfolio integration features:

Support for IP NAT Outside

Starting from ArubaOS 7.4, Mobility Access Switch provides support for IP NAT outside on egress VLAN interface. The IP NAT outside feature changes the source IP of all the egressing packets to the IP of the egress VLAN interface. You can configure IP NAT outside using the CLI. For more information on configuring IP NAT Outside, see *ArubaOS 7.4 User Guide*.

Support for Dynamic Domain Name Server Client

Starting from ArubaOS 7.4, Mobility Access Switch provides support for Dynamic DNS Client. The Dynamic DNS Client enables a Mobility Access Switch to update its DHCP assigned IP address with a Dynamic DNS service provider. This helps to keep the remote devices reachable without tracking their IP address. For more information on DDNS configuration, see *ArubaOS 7.4 User Guide*.

Support for Myonlineportal.net

Starting from ArubaOS 7.4.0.1, Mobility Access Switch extends support for the **myonlineportal.net** dynamic DNS server in addition to the other servers supported in ArubaOS 7.4.

Aruba VPN Tunnel

The Mobility Access Switch at the branch acts as the VPN endpoint and the controller at the datacenter acts as the VPN concentrator. When a Mobility Access Switch is set up for VPN, it forms an IPsec tunnel to the controller to secure sensitive corporate data. IPsec authentication and authorization between the controller and the Mobility Access Switches is based on the RAP whitelist configured on the controller.



You can configure an Aruba VPN tunnel either manually or through Zero Touch Provisioning (ZTP).

For more information on ZTP VPN and manual configuration of Aruba VPN Tunnel, see *ArubaOS 7.4 User Guide*.

Distributed, L3 DHCP Scopes

Starting from ArubaOS 7.4, Mobility Access Switch allows you to configure the DHCP address assignment for the branches connected to the corporate network through VPN. You can configure the range of DHCP IP addresses used in the branches and the number of client addresses allowed per branch. You can also specify

the IP addresses that must be excluded from those assigned to clients, so that they are assigned statically. This release of Mobility Access Switch provides support for Distributed, L3 DHCP scope.

In Distributed L3 mode, DHCP server resides in the local branch on the Mobility Access Switch and each branch location is assigned a dedicated subnet. Based on the number of clients specified for each branch, the range of IP addresses is divided. Based on the IP address range and client count configuration, the DHCP server is configured with a unique subnet.

For more information on configuring Distributed L3, DHCP Scope, see *ArubaOS 7.4 User Guide*.

NAT Pools

Starting from ArubaOS 7.4, Mobility Access Switch provides support for NAT pools to protect private IPs of trusted servers behind the switch. It also gives the flexibility to support source NAT and dual NAT without using the switch IP. NAT actions can be performed only on packets processed by software. Support for applying session ACLs on RVI enables software processing of the packets that require a NAT action.

For more information on configuring NAT pools, see *ArubaOS 7.4 User Guide*.

VPN Survivability

The Mobility Access Switch provides support for a standby VPN uplink when the primary VPN uplink interface goes down. Whenever the primary uplink is detected to be down, the standby uplink is used to establish VPN.

For more information on configuring VPN Survivability, see *ArubaOS 7.4 User Guide*.

Default Route to VPN

Starting from ArubaOS 7.4, a crypto map matching all destinations can be used for customer applications that require all client generated traffic (Internet and Corporate bound) to be sent over a VPN tunnel. A branch office Mobility Access Switch has VPN tunnel which terminates on a Firewall. Any client non-corporate traffic from Mobility Access Switch is forwarded to the firewall through the VPN tunnel. This requires a default gateway route on Mobility Access Switch pointing to a VPN tunnel.

For more information Default Route to VPN, see *ArubaOS 7.4 User Guide*.

Multiple Default Gateway Support

Default gateway is the route configured on the Mobility Access Switch to reach the upstream network. Starting from ArubaOS 7.4, Mobility Access Switch allows you to configure multiple default gateways using the metric option introduced in the CLI. Gateway with lower metric takes precedence when more than one gateways exist to a given upstream network. The second gateway with higher metric takes over when the first route is down.

For more information on multiple Default gateway support, see *ArubaOS 7.4 User Guide*

Access Point Integration Features

This release of ArubaOS provides support for the following portfolio integration features:

Configurable Rogue AP Containment

Starting from ArubaOS 7.4, the Mobility Access Switch allows you to configure the rogue AP containment using the CLI. This was enabled by default and was not configurable in ArubaOS 7.3.x versions.

You can now enable or disable rogue AP containment and configure the action to be taken on the list of MAC addresses received from IAP that are detected as rogue. The default action is to shut down the access port and PoE on which it is detected and to discard the MAC address of the rogue AP and blacklist it if detected on a trunk port.

This feature is enabled by default. For more information on configuring Rogue AP Containment, see *ArubaOS 7.4 User Guide*.

Dynamic Port Reconfiguration

Starting from ArubaOS 7.4, Mobility Access Switch dynamically configures an interface based on the type of device connected to it. It uses LLDP to detect the type of device connected to an interface and applies a device-group configuration (a set of predefined configuration) on the interface based on the device-type.



In this release, the Mobility Access Switch provides support only for the device-type and Aruba APs that support Aruba's proprietary LLDP TLVAP device-group.

This feature is disabled by default. For more information on reconfiguring ports dynamically, see *ArubaOS 7.4 User Guide*.

Platform Features

This release of ArubaOS provides support for the following platform features:

Restoring Factory Default Settings on S1500

Starting from ArubaOS 7.4.0.2, S1500 Mobility Access Switch allows you to use the **Mode** button to restore the switch to the factory default settings. You can enable this feature by using a CLI command on a configured S1500 Mobility Access Switch. After enabling the feature, you must push and hold the **Mode** button on the switch for about 15 seconds to reset it to the factory defaults. The Mobility Access Switch reboots after the reset.

Configuring Mode Button on S1500

Execute the following commands to enable the **Mode** button for factory reset:

```
(host) (config) #mode-button
(host) (mode-button) #enable factory-default
```

Verifying Mode Button Configuration

Use the following command to verify the **Mode** button configuration:

```
(host) #show mode-button
mode-button (N/A)
-----
Parameter      Value
-----
factory-default  enabled
```

Platform Enhancements

Starting from ArubaOS 7.4, the following enhancements are introduced in the Mobility Access Switch:

- DAC support on S1500 (GE Only)
- 10GBASE-ER SFP+
 - 40km over SMF
- 10GBASE-ZR SFP+
 - 80km over SMF

WebUI Enhancements

Starting from ArubaOS 7.4.1, the column header in the **Dashboard > Ports** page of the Mobility Access Switch WebUI is changed from **Total Errors** to **Total Error Frames** to indicate that the error counter refers to the frames counter.

Resolved Issues

This release of ArubaOS includes fixes for [CVE-2015-0286](#) and [CVE-2015-0292](#). Additionally, this section lists the issues that are resolved until ArubaOS 7.4.1:

AirWave/Activate

Table 7: Fixed AirWave/Activate Issues

Bug ID	Description	Fixed in
108372	Symptom: The AirWave details obtained through DHCP options (60 and 43) were not retained by a Mobility Access Switch after a reload. Scenario: This issue was observed in Mobility Access Switches running ArubaOS 7.3 or later versions when in factory default settings.	7.4.0.1

Base OS Security

Table 8: Fixed Base OS Security Issues

Bug ID	Description	Fixed in
113613	Symptom: The Invalid downloadable role error messages were reported incorrectly on the Mobility Access Switch. Scenario: This issue was not limited to any specific Mobility Access Switch model or release version.	7.4.0.3
110867	Symptom: The extended ACL keyword, established was not effective for the traffic processed in the hardware. Scenario: This issue was not limited to any specific Mobility Access Switch model or release version.	7.4.0.2
105743	Symptom: A Mobility Access Switch crashed and rebooted due to a synchronization issue with the AAA user table. Scenario: This issue was not limited to any specific Mobility Access Switch model or release version.	7.4.0.1
105890	Symptom: The administrators were unable to login to the Mobility Access Switch using the console for a brief period. The logs indicated that the kernel killed an internal process with the following out of memory message: nanny[1345]: <303093> <ERRS> nanny Out Of Memory handler killed process /mswitch/bin/aaa_proxy:1380 due to low memory. Set 1 Scenario: This issue was not limited to any specific Mobility Access Switch model or release version.	7.4.0.1
107099	Symptom: The log operator applied on an ACL was not effective when the ACL was applied to a Routed VLAN interface. Scenario: This issue was not limited to any specific Mobility Access Switch model or release version.	7.4.0.1
85582	Symptom: Quate CMS cross site scripting (XSS) vulnerabilities were noticed in the system. This issue is resolved by upgrading OpenSSL and Apache HTTP. Scenario: This issue was not limited to any specific Mobility Access Switch model or release version.	7.4

Captive Portal

Table 9: Fixed Captive Portal Issues

Bug ID	Description	Fixed in
115518	<p>Symptom: Users could not access the allowed Web sites through Captive Portal as the whitelist ACLs were lost on the switch after a reboot or an internal process restart.</p> <p>Scenario: This issue was observed if Whitelist was configured in the Captive Portal profile. This issue was not limited to any specific Mobility Access Switch model or release version.</p>	7.4.1

Configuration

Table 10: Fixed Configuration Issues

Bug ID	Description	Fixed in
112282	<p>Symptom: A crash due to memory issues was observed in a Mobility Access Switch managed through AirWave.</p> <p>Scenario: This issue was observed in Mobility Access Switches running ArubaOS 7.3.0.1 when configured and managed through AirWave.</p>	7.4.1
106082	<p>Symptom: The CLI did not process a command that exceeded 252 characters. This issue is fixed by increasing the maximum command-line character limit to 512.</p> <p>Scenario: This issue was not limited to any specific Mobility Access Switch model or release version.</p>	7.4.0.1
93768	<p>Symptom: Multiple mirroring profiles creation was not allowed. This issue is resolved by allowing creation of multiple mirroring profiles. However, at a given time, only one mirroring profile can be applied to different interfaces.</p> <p>Scenario: This issue was not limited to a specific Mobility Access Switch model or release version.</p>	7.4
94375	<p>Symptom: Authenticated clients were unable to pass traffic causing a network outage. This issue is resolved by clearing the user table.</p> <p>Scenario: This issue was observed when MAC address of the uplink interface was learnt on untrusted interface. This issue was observed on Mobility Access Switches running ArubaOS 7.3.2.1</p>	7.4

Data Path Agent

Table 11: Fixed Data Path Agent Issues

Bug ID	Description	Fixed in
105466	Symptom: The DPA process crashed when there were too many user updates in a fully loaded system. Scenario: This issue occurred when a system with untrusted users had a lot of user updates in multiple VLANs. This issue was observed in Mobility Access Switches running ArubaOS 7.3 or later versions.	7.4.0.2
99566	Symptom: The DPA process crashed on the Mobility Access Switch. Scenario: This issue occurred when a user pressed the MODE button on the front panel of the Mobility Access Switch during the boot process. This issue was observed in S1500-12P model running ArubaOS 7.3.0.1 or earlier versions.	7.4

DHCP

Table 12: Fixed Data Path Agent Issues

Bug ID	Description	Fixed in
104220	Symptom: The Mobility Access Switch incorrectly leased out an IP address that was used by another client. Scenario: This issue was observed when the DHCP server pool on the Mobility Access Switch had only one IP address to offer. This issue was not limited to any specific Mobility Access Switch model or release version.	7.4.0.3

Generic Routing Encapsulation (GRE)

Table 13: Fixed GRE Issues

Bug ID	Description	Fixed in
112619	Symptom: A GRE tunnel could not be established between a Mobility Access Switch and a controller when a non-zero value was configured for the tunnel type on the Mobility Access Switch. Scenario: This issue was observed when the Mobility Access Switch was trying to connect to a controller running ArubaOS 6.4 or later versions.	7.4.0.2

IPSec

Table 14: Fixed IPSec Issues

Bug ID	Description	Fixed in
85235	<p>Symptom: Traffic outage occurred when re-keying of the VPN tunnel failed. This issue is resolved by enabling the NAT-T option in configuration because traffic is across WAN.</p> <p>Scenario: This issue was observed in a WAN deployment where VPN tunnel was established and re-keying of the tunnel was set to be executed every hour. However, VPN tunnel failed to re-key after every 6 to 8 hours causing traffic outage. But at the next re-key interval (after one hour), the re-keying was successful and allowed traffic.</p>	7.4

Layer 2 Forwarding

Table 15: Fixed Layer 2 Forwarding Issues

Bug ID	Description	Fixed in
109561	<p>Symptom: A disruption in the network traffic was sometimes observed in an ArubaStack. Users sometimes encountered the following error message upon executing any layer 2 CLI command: Module Layer 2 manager is busy</p> <p>Scenario: This issue occurred if a stack member disconnected and re-joined the ArubaStack when spanning tree was enabled. This issue was observed in an ArubaStack running ArubaOS 7.3.x or later versions.</p>	7.4.0.2
107450	<p>Symptom: The process handling layer 2 functions crashed when the Mobility Access Switch received LLDP BPDUs with System Description exceeding 256 bytes.</p> <p>Scenario: This issue was observed in Mobility Access Switches running ArubaOS 7.4.</p>	7.4.0.1

Multicast

Table 16: Fixed Multicast Issues

Bug ID	Description	Fixed in
93220	<p>Symptom: Domain login takes unusually long time when the traffic goes through tunnel node. This issue was resolved by changing the configuration to use TCP instead of UDP so that the server does not expect packets in sequence.</p> <p>Scenario: This issue was observed when the kerb client was connected to tunneled node port, and the client sent packets exceeding tunnel MTU. This issue was not limited to any specific Mobility Access Switch model or release version.</p>	7.4

OSPF

Table 17: *Fixed OSPF Issues*

Bug ID	Description	Fixed in
98544	<p>Symptom: OSPF convergence time was longer (about 45 seconds) in a Mobility Access Switch. The convergence time is now reduced to 30 seconds by changing the default value of hello interval time and dead interval time to 7 and 28 seconds from 10 and 40 seconds, respectively.</p> <p>NOTE: OSPF neighbors trying to form an adjacency with a Mobility Access Switch running ArubaOS 7.4.1 must have the value for hello interval time matching with that of the Mobility Access Switch.</p> <p>Scenario: This issue was observed when OSPF was configured on a Mobility Access Switch. This issue was not limited to any specific Mobility Access Switch model or release version.</p>	7.4.1

RADIUS

Table 18: *Fixed RADIUS Issues*

Bug ID	Description	Fixed in
107183	<p>Symptom: The following debug message was incorrectly reported in the error logs of the Mobility Access Switch as the accounting messages were incorrectly sent for the unauthenticated users:</p> <p>An internal system error has occurred at file rc_acct.c print</p> <p>Scenario: This issue was observed in Mobility Access Switches running ArubaOS 7.3.2.1 or later versions when interim accounting was enabled in the AAA profile.</p>	7.4.0.1

Routing

Table 19: *Fixed Routing Issues*

Bug ID	Description	Fixed in
110596	<p>Symptom: The following error message appeared when executing the command, clear ip ospf process on the Mobility Access Switch: Module Layer 3 Manager is busy. Please try later</p> <p>Scenario: The issue occurred if the command was executed when a default OSPF route or a router IP that conflicted with the tunnel destination IP was advertised through GRE over VPN tunnel. This issue was observed in Mobility Access Switches running ArubaOS 7.3 or later versions.</p>	7.4.0.2
109727	<p>Symptom: A Mobility Access Switch failed to respond to ARP requests for an IP used in a NAT pool even though session-processing was enabled on the uplink VLAN.</p> <p>Scenario: This issue was observed when a session ACL was applied on a VLAN that had a source NAT configured from a NAT pool. This issue was limited to Mobility Access Switches running ArubaOS 7.4.</p>	7.4.0.1
109920	<p>Symptom: The following error message was displayed on a Mobility Access Switch when executing any layer 3 command in the CLI: Module Layer3 Manager is busy. Please try later</p> <p>The message logs indicated that the module handling the layer 3 functions had crashed.</p> <p>Scenario: The crash occurred when a default OSPF route or a router IP that conflicted with the tunnel destination IP was advertised through GRE over VPN tunnel. This issue was observed in Mobility Access Switches running ArubaOS 7.3 or later versions.</p>	7.4.0.1

Stacking

Table 20: *Fixed Stacking Issues*

Bug ID	Description	Fixed in
94551	<p>Symptom: The output of show stacking members command displayed more than eight members with valid member IDs even though Mobility Access Switch supports only up to eight members in an ArubaStack. This issue is resolved by ensuring that a maximum of eight members are only allowed in an ArubaStack.</p> <p>Scenario: This issue was observed when more than eight members were added to the ArubaStack. This issue was not specific to any Mobility Access Switch model or release version.</p>	7.4
95855	<p>Symptom: The Primary member of a 5 member ArubaStack rebooted due to memory leak.</p> <p>Scenario: The issue occurred when LLDP was enabled in the ArubaStack. This issue was limited to ArubaStack with S3500 Mobility Access Switches running ArubaOS 7.3.0 or later.</p>	7.4
103518	<p>Symptom: The Mobility Access Switch displayed the Module Layer 2 manager is busy error message on issuing any CLI command.</p> <p>Scenario: This issue occurred during a system switchover or Layer 2 Module (L2M) process restart. This issue was observed in Mobility Access Switches running ArubaOS 7.3.2.2 or earlier versions.</p>	7.4

Switch-Datapath

Table 21: Fixed Switch-Datapath Issues

Bug ID	Description	Fixed in
113397	Symptom: Sometimes, the clients connected to a Mobility Access Switch obtained an IP address from the initial VLAN instead of the final VLAN. Scenario: This issue was not limited to any specific Mobility Access Switch model or release version.	7.4.0.3
113448	Symptom: DHCP broadcast packets were dropped by ingress RVI ACL configured on a Mobility Access Switch. Scenario: This issue was observed in Mobility Access Switches running ArubaOS 7.4.0.1.	7.4.0.2
97002	Symptom: The Mobility Access Switch dropped packets when the traffic rate was high on the egress port due to insufficient port buffer. Scenario: The issue was not limited to any specific Mobility Access Switch model or release version.	7.4

Switch-Platform

Table 22: Fixed Switch-Platform Issues

Bug ID	Description	Fixed in
112286	Symptom: The following error message was displayed on a Mobility Access Switch a few minutes after executing any Layer 3 show command in the CLI: Module Layer3 Manager is busy. Please try later. Scenario: This issue was observed when a large number of hosts were connected to the Mobility Access Switch. This issue was not limited to any specific Mobility Access Switch model or release version.	7.4.1
113966	Symptom: The Mobility Access Switch WebUI did not display all the stacking ports correctly. Scenario: This issue was observed in an ArubaStack running ArubaOS 7.3 or later versions.	7.4.0.3
114628	Symptom: Transceivers connected to a Mobility Access Switch were not detected when the Mobility Access Switch was reloaded after an image upgrade or downgrade. Scenario: This issue was observed when there were multiple transceivers connected to the Mobility Access Switch running ArubaOS 7.4.0.2.	7.4.0.3
111206	Symptom: The process handling layer 3 functions crashed when Dyn DNS was enabled on a Mobility Access Switch. Scenario: This issue was observed in Mobility Access Switches running ArubaOS 7.4.0.1.	7.4.0.2

Table 22: Fixed Switch-Platform Issues

Bug ID	Description	Fixed in
98030	<p>Symptom: A stack member stopped responding and rebooted.</p> <p>Scenario: The log files for the event suggested multiple link flaps. Due to this, the Chassis Manager (CM) process missed keep-alives and removed the stack member from the ArubaStack. This issue was observed in Mobility Access Switches running ArubaOS 7.2.2.2.</p> <p>NOTE: This issue was caused due to a cabling problem at the customer site.</p>	N/A
89131 95757 104999	<p>Symptom: Crash file was unavailable for a crash due to kernel panic. This issue is resolved by adding the watchdog and Non Maskable Interrupt (NMI) support.</p> <p>Scenario: This issue occurred because of synchronization problems in the panic routine. This issue was not limited to a specific Mobility Access Switch model or release version</p>	7.4
99562	<p>Symptom: The Mobility Access Switch stopped detecting SFP/SFP+ transceivers when they were plugged out and inserted back in, or replaced.</p> <p>Scenario: This issue was observed in Mobility Access Switches running ArubaOS 7.3.1.0 or earlier versions.</p>	7.4

WebUI

Table 23: Fixed WebUI Issues

Bug ID	Description	Fixed in
105975	<p>Symptom: Copy Backup option in WebUI did not redirect to the Copy files page after upgrading the Mobility Access Switch from ArubaOS 7.2 to 7.3.2.2.</p> <p>Scenario: This issue occurred when ArubaOS was upgraded to 7.3 or later versions on the Mobility Access Switches.</p>	7.4.0.1
104261	<p>Symptom: The Allowed VLAN field under the Configuration > Ports > Switching tab was inaccessible through the WebUI of the Mobility Access Switch.</p> <p>Scenario: This issue occurred when the Mobility Access Switch was upgraded from ArubaOS 7.3.1.0 to ArubaOS 7.3.2.0. This issue was observed in Mobility Access Switches running ArubaOS 7.3.2.0 or later versions.</p>	7.4

Known Issues and Limitations

The following are known issues and limitations observed in ArubaOS 7.4.1. Bug IDs and applicable workarounds are included.

Base OS Security

Table 24: *Known Base OS Security Issues and Limitations*

Bug ID	Description
74264	<p>Symptom: A combination of CPPM and Windows Radius server for fail-through is not supported.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model or release version.</p> <p>Workaround: Use either CPPM servers as Primary and Backup or Windows Radius as Primary and Backup. Do not combine them.</p>
87971	<p>Symptom: The Mobility Access Switch IP is programmed as the loopback IP automatically when there is no ip-cp redirect address configured. If ip-cp redirect address is configured and saved in the config, either system switchover or reload is invoked. After switchover or reload the configured ip-cp redirect address is lost. The IP address displays all 0s.</p> <p>Scenario: This issue occurs only when the ip cp-redirect-address<ip-addr> command is configured on Mobility Access Switches running ArubaOS 7.3.</p> <p>Workaround: If the ip-cp redirect address command is explicitly configured and it is lost after reload or switchover, configure the ip cp-redirect-address<ip-addr> command once again and save it.</p>
90067	<p>Symptom: A ClearPass Policy Manager (CPPM) Downloadable Role may not be properly assigned to a Mobility Access Switch user if it is not correctly configured in CPPM.</p> <p>Scenario: This issue occurs when the Mobility Access Switch is still processing the invalid Downloadable Role and an administrator has already modified the Downloadable Role in CPPM. This issue occurs on Mobility Access Switches running ArubaOS 7.3.</p> <p>Workaround: Ensure that the role definition syntax is correct in CPPM. This can be verified by testing the configuration on a test switch before configuring the role details in CPPM. If that is not possible and a Downloadable Role has been incorrectly defined, wait for the Mobility Access Switch to complete processing the invalid role (~3 minutes), delete the user(s) assigned to that role, update the role definition in CPPM and re-trigger authentication.</p>
100904	<p>Symptom: When a client successfully authenticated by MAC and/or dot1x authentication fails reauthentication, it remains in the authenticated VLAN even after it moves back to the previous role.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model or release version.</p> <p>Workaround: Delete the failed user entry manually.</p>
101489	<p>Symptom: When an authenticated client fails reauthentication after an EAP-start, it remains in the previously authenticated role and VLAN.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model or release version.</p> <p>Workaround: Delete the failed user entry manually.</p>

Table 24: *Known Base OS Security Issues and Limitations*

Bug ID	Description
114450	<p>Symptom: An authenticated user is not assigned the default authentication role when the role download from CPPM fails.</p> <p>Scenario: This issue is observed in S2500 and S3500 Mobility Access Switches running ArubaOS 7.4.0.2.</p> <p>Workaround: None.</p>
114452	<p>Symptom: Users cannot create NAT pools using a downloadable role in CPPM though NAT pools can be referenced from CPPM.</p> <p>Scenario: This issue occurs when the Mobility Access Switch tries to download NAT Pool configuration from CPPM. This issue is observed in Mobility Access Switches running ArubaOS 7.3 or later versions.</p> <p>Workaround: None.</p>
120783	<p>Symptom: The authentication (auth) servers that are marked as out-of-service are not cleared from the server-group table—even after executing the auth-server command—until the dead timer expires.</p> <p>Scenario: This issue is observed in S2500 and S3500 Mobility Access Switches running ArubaOS 7.4.x.</p> <p>Workaround: Execute the following command to bring the auth server back to service: <pre>aaa inservice <server-group> <authentication-server></pre></p>

Central

Table 25: *Known Central Issues and Limitations*

Bug ID	Description
102328	<p>Symptom: When the Mobility Access Switch is in managed mode, the configuration received or sent from Aruba Central are not processed and applied properly, if the size of running-config file exceeds 150KB.</p> <p>Scenario: This issue occurs when the Mobility Access Switch has a large number of profile configuration defined and managed by Aruba Central. This issue is observed on a standalone Mobility Access Switch running ArubaOS 7.3.2 or later versions.</p> <p>Workaround: None.</p>
104181	<p>Symptom: Users are unable to configure the Mobility Access Switch from the console for 5 to 10 mins after it loses connection from Aruba Central.</p> <p>Scenario: This issue occurs when the Mobility Access Switch in Managed mode abruptly disconnects from Aruba Central. This issue is observed on a standalone Mobility Access Switch running ArubaOS 7.3.2.2 or later versions.</p> <p>Workaround: None.</p>

Configuration

Table 26: *Known Configuration Issues and Limitations*

Bug ID	Description
55306	<p>Symptom: User is unable to delete the characters using the backspace key when the admin username is as long as the maximum characters.</p> <p>Scenario: This issue is observed when the admin username reaches the maximum limit (32 characters). This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: Press enter key and type the username again.</p>
99871	<p>Symptom: Sometimes, the user prompt does not appear on the Mobility Access Switch console after a reload.</p> <p>Scenario: This issue is observed only when a Mobility Access Switch running ArubaOS 7.4 is reloaded.</p> <p>Workaround: Press any key to proceed with the login.</p>
101284	<p>Symptom: The local IP address of the NTP servers are displayed as 0.0.0.0 when executing the show ntp servers command after rebooting the Mobility Access Switch. This occurs because the NTPD is not refreshed with the switch IP address.</p> <p>Scenario: This issue is observed only when a Mobility Access Switch running ArubaOS 7.3 or later version is rebooted.</p> <p>Workaround: Remove and reconfigure the NTP servers.</p>
101943	<p>Symptom: Users cannot configure the banner MOTD text using the banner motd command in the same line.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model or release version.</p> <p>Workaround: Enter the banner text to be configured with a delimiter in a new line after the banner motd keyword.</p>

DHCP Snooping

Table 27: *Known DHCP Snooping Issues and Limitations*

Bug ID	Description
87131	<p>Symptom: When a line card member of an ArubaStack is individually rebooted, the DHCP Snooping bindings for that particular member switch are lost.</p> <p>Scenario: Reloading a line card does not trigger repopulating the DHCP Snooping database. However, the DHCP Snooping database repopulates in case of a stack or box reload. This issue occurs on Mobility Access Switches running ArubaOS 7.3.</p> <p>Workaround: None.</p>

Data Path Agent (DPA)

Table 28: *Known DPA Issues and Limitations*

Bug ID	Description
98845	<p>Symptom: The DPA process crashes on the Mobility Access Switch.</p> <p>Scenario: This issue is observed when the DPA process waits for an acknowledgment from the SOS process and times out. This issue is observed in Mobility Access Switches running ArubaOS 7.3.0.1 or later versions.</p> <p>Workaround: None.</p>

Dynamic ARP Inspection (DAI)

Table 29: Known DAI Issues and Limitations

Bug ID	Description
91146	<p>Symptom: An ACL matching on ARP traffic for specific source and destination pairs may not always be enforced.</p> <p>Scenario: This issue is observed only when Dynamic ARP Inspection (DAI) is enabled on the Mobility Access Switch and is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: Disable DAI when using ACLs matching on ARP for specific source and destination pairs.</p>

Generic Routing Encapsulation (GRE)

Table 30: Known GRE Issues and Limitations

Bug ID	Description
87459 88968	<p>Symptom: L3 GRE tunnel interfaces toggles between up and down states.</p> <p>Scenario: This issue occurs when the L3 GRE tunnel forwarding rate exceeds 40 Kilo packets per second (Kpps). This issue occurs in Mobility Access Switches running ArubaOS 7.3.</p> <p>Workaround: None.</p>

Interface

IPsec

Table 31: Known IPsec Issues and Limitations

Bug ID	Description
73261	<p>Symptom: Site-to-site IPsec VPN with transport-mode is not functioning correctly.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model or release version.</p> <p>Workaround: None.</p>
94073	<p>Symptom: The IKE gets deleted when the Mobility Access Switch is used as a NAT box.</p> <p>Scenario: This issue is observed when the session-idle-timeout value was less than the DPD timer value. This issue is not limited to any specific Mobility Access Switch model or release version.</p> <p>Workaround: Use the crypto-local isakmp dpd idle-timeout <idle_sec> command to reduce the DPD time to a value lower than the session-idle-timeout value configured under the firewall command.</p>
103560	<p>Symptom: The crypto isakmp pre-shared key does not accept special characters to establish an IKE session.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model or release version.</p> <p>Workaround: None.</p>

IPv6

Table 32: *Known IPv6 Issues and Limitations*

Bug ID	Description
57529	<p>Symptom: Copy on IPv6 address does not work as this command is not recognized for IPv6. As a result, the scp/ftp/tftp copy over IPv6 address will not work.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: Use an IPv4 address instead of an IPv6 or use the WebUI and try the local file management.</p>

Layer 2 Forwarding

Table 33: *Known Layer 2 Forwarding Issues and Limitations*

Bug ID	Description
68312	<p>Symptom: DHCP Offer/ACK messages are not discarded when using DHCP Trust .</p> <p>Scenario: This issue is observed when no trust DHCP is enabled in a port- security profile and a MAC ACL with a permit any any rule is applied to an interface. This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: Use a stateless ACL instead of a MAC ACL.</p>
73285	<p>Symptom: The Mobility Access Switch does not register a GVRP VLAN on the STP blocked ports.</p> <p>Scenario: This issue occurs when there is a change in the STP topology and the blocked ports become forward. The ports first register the VLAN and then the data traffic flow continues. Under these conditions, there is a long delay in resuming the traffic.</p> <p>Workaround: None.</p>

Multicast

Table 34: *Known Multicast Issues and Limitations*

Bug ID	Description
63951	<p>Symptom: As IPv6 on untrusted port is not supported in this release, Multicast Listener Discovery (MLD) snooping on untrusted port is ignored. Hence, MLD snooping membership table cannot be formed.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: None.</p>
65314	<p>Symptom: The Mobility Access Switch does not send query when there is a change in the Spanning Tree Protocol (STP) topology. This delays the formation of the MLD snooping membership table.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: None.</p>
77185	<p>Symptom: IGMP Snooping entries are removed in 12 seconds before expiry of the age-out timer.</p> <p>Scenario: This issue is observed when mutlicast stream is sent over 40Kpps on a L2 GRE tunnel. This issue is not limited to any specific Mobility Access Switch version.</p> <p>Workaround: Send multicast stream less than 40 Kpps over a L2 GRE tunnel.</p>

OSPF

Table 35: *Known OSPF Issues and Limitations*

Bug ID	Description
59609	<p>Symptom: Layer 3 Manager utilizes more memory and throws an error message during the removal of large number of OSPF routes.</p> <p>Scenario: This issue is observed in S3500 running ArubaOS 7.2.0.0.</p> <p>Workaround: None.</p>
59738	<p>Symptom: Loss of traffic is observed on some advertised OSPF routes.</p> <p>Scenario: This issue is observed when it reaches the route capacity limitation (1500). This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: None.</p>

Port-Channel

Table 36: *Known Port-Channel Issues and Limitations*

Bug ID	Description
104770	<p>Symptom: Connectivity to devices across port channel results in extended request time out when the member port status is changed.</p> <p>Scenario: This issue is observed under the following configuration setup:</p> <ul style="list-style-type: none">• On Mobility Access Switch, configure port channel in LACP mode.• On Cisco switch, configure port channel.• Configure the link between the two devices as a trunk link. <p>This issue is observed in S2500 running ArubaOS 7.3.2.1.</p> <p>Workaround: None.</p>

QoS

Table 37: *Known QoS Issues and Limitations*

Bug ID	Description
79774	<p>Symptom: The Mobility Access Switch does not apply QoS remarking or prioritization for traffic in an L2 GRE tunnel.</p> <p>Scenario: A QoS profile configured on the interface of the Mobility Access Switch does not prioritize traffic in an L2-GRE tunnel traversing through the same interface. This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: None.</p>

Routing

Table 38: *Known Routing Issues and Limitations*

Bug ID	Description
84327	<p>Symptom: Traffic continues to be routed even though the ingress Routed Virtual Interface (RVI) is administratively shutdown.</p> <p>Scenario: If any Layer 3 unicast traffic is received destined to an RVI that is in an administratively down state, the RVI will route the unicast traffic towards destination even though it is shutdown. This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: None.</p>
74123	<p>Symptom: With Source NAT enabled, no matter what MTU value is assigned to the RVI, packets up to 1784 bytes will be source NAT'ed. Packets larger than this are dropped on the ingress RVI because fragmentation is not supported. Additionally, no matter what MTU is configured, packets leaving the egress RVI are not fragmented.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model or release version.</p> <p>Workaround: None.</p>
103209	<p>Symptom: The routing table sometimes contains routes for the reserved multicast IP addresses of IGMPv3.</p> <p>Scenario: This issue is observed when L3 GRE tunnel is configured with OSPF routing protocol. This issue is limited to Mobility Access Switches running ArubaOS 7.4</p> <p>Workaround: None.</p>
105540	<p>Symptom: The peer IP route configured in the crypto map points to the default gateway even though a static route is configured for the peer IP.</p> <p>Scenario: This issue is limited to Mobility Access Switches running ArubaOS 7.4.</p> <p>Workaround: Configure a higher metric on the VLAN interface through which the peer IP is reachable.</p>
105550	<p>Symptom: Sometimes, the connected routes on a VLAN interface may not appear in the routing table after a switchover.</p> <p>Scenario: This issue is observed when the VLAN interface with a dynamic IP address is configured on a port channel. This issue is observed on Mobility Access Switches running ArubaOS 7.4.</p> <p>Workaround: None.</p>

Security

Table 39: *Known Security Issues and Limitations*

Bug ID	Description
64356	<p>Symptom: Router Advertisement (RA) messages are not dropped on untrusted interfaces.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: None.</p>
67157	<p>Symptom: If a phone connected to a Mobility Access Switch port using 802.1X MD5 authentication experiences an Extensible Authentication Protocol (EAP) transaction failure, the Mobility Access Switch sends an EAP-Fail packet every 5 seconds after the failure until the phone restarts 802.1X authentication.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: None.</p>
67159	<p>Symptom: If a phone connected to a Mobility Access Switch port using 802.1X authentication and the AAA profile bound to the interface has a user-derivation rule associated with it, the phone may exchange multiple EAP transactions with the Mobility Access Switch, but may not be able to complete the 802.1X authentication.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: Remove the user-derivation-rule from the AAA profile.</p>
82617	<p>Symptom: When Captive Portal authentication is provided by ClearPass Guest, instead of assigning a Downloadable Role with Captive Portal redirect, the user gets the default Captive Portal user role defined in the Captive Portal settings.</p> <p>Scenario: The issue was observed when the user table has two L3 entries for a same MAC. This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: Delete both the stale and valid user entry and perform Captive Portal authentication again.</p>
84802	<p>Symptom: A Cisco® IP phone that is assigned a user-role via a device-type User Derivation Rule (UDR) and also 802.1X authenticated (UDR user-role overrides 802.1X user-role), shows the authentication type as Web as opposed to 802.1X-Wired after a switchover of the primary and secondary ArubaStack members.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: The show user ip <A.B.C.D> command incorrectly displays Web under the Auth column for a Cisco IP phone connected to the Mobility Access Switch. However, the switch assigns the correct role to the Cisco IP phone.</p>
85674	<p>Symptom: For some IP phones, the show station-table command entry displays the MAC or 802.1X default authentication role of the AAA profile. However, the show user-table command entry displays the initial role of the AAA profile.</p> <p>Scenario: This issue occurs when an IP phone connected to one of the ports of the Mobility Access Switch, gets an IP address before an L2 authentication completes. This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: None.</p>
85682	<p>Symptom: When 802.1X authentication is configured with Extensible Authentication Protocol (EAP) termination, even if the user gets black-listed it is still able to re-attempt authentication prior to the black-list timer expiring.</p> <p>Scenario: This issue is observed when 802.1X authentication with EAP termination type is set to eap-tls and inner-eap-type is set to EAP-General Token Type (GTC). This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: None.</p>

SNMP

Table 40: *Known SNMP Issues and Limitations*

Bug ID	Description
82812	<p>Symptom: SNMP may not respond temporarily due to a process crash.</p> <p>Scenario: This issue is observed while issuing an SNMP GetNext on the ipNetToMediaTable. This issue occurs in Mobility Access Switch running 7.2.0.0 or later and not limited to any specific model.</p> <p>Workaround: None.</p>

Stacking

Table 41: *Known Stacking Issues and Limitations*

Bug ID	Description
92339	<p>Symptom: Multicast packets in an S1500 ArubaStack are rate limited to 40kpps when IGMP-snooping is enabled on a Rendezvous Point interface.</p> <p>Scenario: This issue is limited to S1500 ArubaStack where PIM-Sparse Mode and IGMP-Snooping are enabled on the ArubaStack and affects clients that are not on the same member as that of the interface connecting to the Rendezvous Point.</p> <p>Workaround: None.</p>

STP

Table 42: *Known STP Issues and Limitations*

Bug ID	Description
57519	<p>Symptom: With Spanning Tree loopguard enabled, an interface will enter LOOP_Inc state if that interface is not receiving any more BPDU.</p> <p>Scenario: When the situation happens, restart L2M daemon (such as doing stacking primary failover) may mistakenly bring the interface back to DES/FWD state.</p> <p>Workaround: Check your network when an interface enters LOOP_Inc state. Resolve your network problem before doing stacking primary failover or L2M restart.</p> <p>NOTE: A typical problem that causes an interface not to receive BPDU happens on the fiber connection in which TX is successful but RX fails.</p>
91798	<p>Symptom: After multiple recoveries on a BPDU guard enabled interface, BPDU guard may take a long time to trigger the shutdown operation on the interface.</p> <p>Scenario: This issue is observed when a Mobility Access Switch or a connected downstream hub/switch is looped upon itself and if BPDU guard is enabled on the connected interfaces. This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: None.</p>
92327	<p>Symptom: In an MSTP topology, the interfaces of the Mobility Access Switches may go into an STP boundary state if the STP mode is manipulated.</p> <p>Scenario: This issue is observed if the STP Mode is manually changed from MSTP to PVST and then changed back to MSTP in any one of the Mobility Access Switches connected in a spanning tree environment. This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: Remove the MSTP instance from VLAN mapping and add it back.</p>

Switch-Datapath

Table 43: *Known Switch-Datapath Issues and Limitations*

Bug ID	Description
58584	<p>Symptom: When an AP is connected to a Mobility Access Switch through a mid-span PoE injector, auto negotiation might fail.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model or release version.</p> <p>Workaround: Force link speed on the ports.</p>

Switch-Platform

Table 44: *Known Switch-Platform Issues and Limitations*

Bug ID	Description
52196	<p>Symptom: Press 'q' to abort does not work after issuing the ping interval <delay_pkts> <host> command.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: None.</p>
65618	<p>Symptom: The Mobility Access Switch does not synchronize with a Network Time Protocol (NTP) server.</p> <p>Scenario: This issue is observed when a NTP server entry is configured prior to configuring or changing the IP address of the egress Routed Virtual Interface (RVI) which is used to contact said NTP server. This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: First configure the IP address the RVI and then configure the NTP server address.</p>
65807	<p>Symptom: When you create an eth ACL with permit any, apply the ACL to a user-role, and send IPv6 traffic to untrusted port, the Mobility Access Switch did not create an L2 user nor forward the IPv6 traffic. ArubaOS 7.3 does not support IPv6 on untrusted port.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: None.</p>
68091	<p>Symptom: An interface is operationally down.</p> <p>Scenario: This issue occurs when an Ethernet OAM failure may still transmit data and other control packets.</p> <p>Workaround: Enable STP on the interface or configure the link as a port-channel member.</p>
86723	<p>Symptom: Copying files from any source to an external USB flash drive or the local flash drive using the CLI does not show the transfer progress and there is no option to abort the transfer.</p> <p>Scenario: This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: None.</p>
86853	<p>Symptom: Copying a raw image from a USB connected to the primary stack member copies the image only on primary and not all stack members.</p> <p>Scenario: This issue occurs on Mobility Access Switches running ArubaOS 7.3.</p> <p>Workaround: None.</p>
86857	<p>Symptom: Users cannot exit from Quick-Setup in the CLI using CTRL+C.</p> <p>Scenario: This issue is observed in an ArubaStack when the console port is redirected from a secondary or line card member. This issue is not limited to any specific Mobility Access Switch model.</p> <p>Workaround: Connect the console port to the primary member of the ArubaStack if using Quick-Setup.</p>

Table 44: *Known Switch-Platform Issues and Limitations*

Bug ID	Description
90167	<p>Symptom: AP-220 Series and AP-130 Series may not get powered up when connected to a Mobility Access Switch.</p> <p>Scenario: This issue is observed when both ethernet ports of the access point are connected to the PoE ports of the same Mobility Access Switch. This issue is limited to PoE models of Mobility Access Switch.</p> <p>Workaround: Remove the poe-profile (i.e. disable PoE) from one of the two ports of the Mobility Access Switch that are connected to the access point.</p>
90231	<p>Symptom: Cisco IP phones utilizing pre-standard PoE (also known as legacy power) may lose power after being operational for a long time.</p> <p>Scenario: This issue is limited to PoE models of the Mobility Access Switch.</p> <p>Workaround: Disconnect the phone for a few minutes and reconnect it.</p>
99827	<p>Symptom: Sometimes, the following I2C error messages are observed in the output of show log system command due to an internal processor issue:</p> <ul style="list-style-type: none">• Mar 4 08:22:17 KERNEL: 2:i2c_xls_wait_for_idle: i2c line is busy (status: 0003)• Mar 4 08:22:17 KERNEL: 2:Unable to select i2c mux channel 6• Mar 4 08:22:17 KERNEL: 2:Hard reset to i2c mux on bus 0 address 0x70• Mar 4 08:22:17 KERNEL: 2:Unable to access hw sensor on bus 9 address 0x2d <p>Scenario: This issue is very rarely observed and is not limited to any specific Mobility Access Switch model or release version.</p> <p>Workaround: Reload the box.</p>
103600	<p>Symptom: Uplink port status LED remains in On state even after the link is locally shutdown with 1G SFP.</p> <p>Scenario: This issue is observed only when a 7205 Mobility Controller is connected to the uplink port of the Mobility Access Switch.</p> <p>Workaround: None.</p>
103713	<p>Symptom: Kernel panic is observed in the tar logs of one of the members of the ArubaStack.</p> <p>Scenario: This issue is observed when an IGMPv2 client joins and disconnects from a group where IGMPv3 is enabled. This issue is limited to ArubaStack running ArubaOS 7.4.</p> <p>Workaround: None.</p>
103793	<p>Symptom: All APs associated to a Mobility Access Switch goes down, and the system status LED on the Mobility Access Switch turns blinking amber indicating a major alarm.</p> <p>Scenario: This issue is observed during lightening, thunder storm, or if another PSE is providing inline power to the Mobility Access Switch. This issue is observed in S2500 and S1500-24/48P Mobility Access Switches running ArubaOS 7.2.2 or earlier versions.</p> <p>Workaround: Upgrade the Mobility Access Switch to ArubaOS 7.3.2.1 to benefit from many PoE features introduced in this release version.</p>
105354	<p>Symptom: A Mobility Access Switch stops responding and reboots. The log files for the event listed the reason as Hard Watchdog Reset.</p> <p>Scenario: This issue is observed in S3500 running ArubaOS 7.3.1.0.</p> <p>Workaround: None.</p>

WebUI

Table 45: *Known WebUI Issues and Limitations*

Bug ID	Description
106087	Symptom: Copying an image using TFTP from the WebUI does not upgrade the image on an ArubaStack. Scenario: This issue occurs only when the TFTP copy is tried from the WebUI for an ArubaStack running ArubaOS 7.3.x or later versions. Workaround: Copy the image using the copy tftp command in the CLI.
107809	Symptom: The following error message appears when downloading logs from the Mobility Access Switch using the WebUI: can't query: TimeoutError: DOM Exception 23 Scenario: This issue occurs only when Safari is used as the browser for the WebUI. This issue is limited to Mobility Access Switches running ArubaOS 7.4 or later versions. Workaround: Use browsers such as Google Chrome or Mozilla Firefox to access the WebUI.

Issues Under Investigation

The following are the issues observed in ArubaOS 7.4.1 and are under investigation. The associated Bug IDs are included.

Layer 2 Forwarding

Table 46: *Layer 2 Forwarding Issues Under Investigation*

Bug ID	Description
110300	Symptom: Mobility Access Switches connected with certain Aruba Access Points lose connectivity to the controller when ArubaOS is upgraded on the controller. The message logs indicate that the process handling layer 2 functions has crashed.

Stacking

Table 47: *Stacking Issues Under Investigation*

Bug ID	Description
99121	Symptom: Error octets are seen in Received Statistics (Rx counters) on the stack ports of S2500 and S3500 Mobility Access Switches.

This chapter details the Mobility Access Switch software upgrade procedures. To optimize your upgrade experience and ensure a successful upgrade, read all the information in this chapter before upgrading and follow all the procedures carefully.

Topics in this chapter include:

- [Important Points to Remember on page 49](#)
- [Installing the FIPS Version of ArubaOS 7.4.1 on page 49](#)
- [Before You Upgrade on page 49](#)
- [Save Your Configuration on page 50](#)
- [Upgrading to ArubaOS 7.4.1 on page 50](#)
- [Downgrading after an Upgrade on page 52](#)
- [Before You Call Your Support Provider on page 53](#)

Important Points to Remember

You should create a permanent list of the following information for future use:

- Best practice is to upgrade during a maintenance window. This will limit the troubleshooting variables.
- Resolve any existing issues (consistent or intermittent) before you upgrade.
- List the devices in your infrastructure that are used to provide your wireless users with connectivity (Core switches, radius servers, DHCP servers, firewall, for example).
- Always upgrade the non-boot partition first. If something happens during upgrade, you can switch back to the boot partition. Upgrading the non-boot partition gives you a smoother downgrade path should it be required.
- If you have removed the default stacking interfaces (ports 0/1/2 and 0/1/3) from 7.0.x but plan to use them for stacking purposes after upgrading to ArubaOS 7.3, you must reconfigure them for stacking.

Installing the FIPS Version of ArubaOS 7.4.1

Download the FIPS version of the software from <https://support.arubanetworks.com>.

Before Installing FIPS Software

Before you install a FIPS version of software on a Mobility Access Switch that is currently running a non-FIPS version of the software, you must reset the configuration to the factory default or you will not be able to login to the CLI or WebUI. Do this by running the **write erase** command just prior to rebooting the Mobility Access Switch. This is the only supported method of moving from non-FIPS software to FIPS software.

Before You Upgrade

Run the following checklist before installing a new image on the Mobility Access Switch:

- Ensure that you have at least 60 MB of free flash space (**show storage** command).
- Run the tar crash command to ensure that there are no “process died” files clogging up memory and FTP/TFTP the files to another storage device. To clean up any crash core file, use the tar clean crash command.
- Remove all unnecessary saved files from flash (**delete filename** command).

Save Your Configuration

Before upgrading, save your configuration and back up your Mobility Access Switch data files. Saving your configuration will retain the admin and enable passwords in the proper format.

Saving the Configuration in the WebUI

1. Click on the Configuration tab.
2. Click the Save Configuration button at the top of the screen.

Saving the Configuration in the CLI

Enter the following command in either the enable or configuration mode:

```
(host) #write memory
```

Upgrading to ArubaOS 7.4.1

Read all the following information before you upgrade. Download the latest software image from the Aruba Customer Support web site.

There are three ways to upgrade your software image:

- [Upgrading from the WebUI on page 50](#)
- [Upgrading from the Command Line Interface on page 51](#)
- [Upgrading from your USB using the LCD on page 51](#)



If you are upgrading from 7.0.x to 7.3 and are going to create a stack, each Mobility Access Switch in the stack must be upgraded to ArubaOS 7.3 before forming the stack.

Upgrading from the WebUI

The following steps describe how to install the Aruba software image from a PC or workstation using the WebUI on the Mobility Access Switch. You can also install the software image from a TFTP or FTP server using the same WebUI page.

1. Upload the new software image to a PC or workstation on your network.
2. Log in to the WebUI from the PC or workstation.
3. Navigate to the **Maintenance > Image Management** page. Select the **Upgrade using local file** option, then click **Browse** to navigate to the image file on your PC or workstation.
4. Determine which partition will be used to hold the new software image. Best practice is to load the new image onto the non-boot partition. To see the current boot partition, navigate to the **Maintenance > Boot Parameters** page.
5. Select **Yes** in the **Reboot after upgrade** field to reboot after upgrade.
6. Click **Upgrade Image**. The image, once copied to the ArubaStack primary, will be pushed down to every stack member.
7. When the software image is uploaded to the Mobility Access Switch, a popup appears. Click **OK** to reload the entire stack. The boot process starts automatically within a few seconds.
8. When the boot process is complete, log in to the WebUI and navigate to the **Monitoring > Summary** page to verify the upgraded code version.
9. Select the **Configuration** tab.
10. Click **Save Configuration** at the top of the screen to save the new configuration file header.

Upgrading from the Command Line Interface

The following steps describe how to install the ArubaOS software image using the CLI on the Mobility Access Switch. You need a FTP/TFTP server reachable from the Mobility Access Switch you are upgrading.

1. Upload the new software image to your FTP/TFTP server on your network.
2. Execute the ping command to verify the network connection from the target Mobility Access Switch to the FTP/TFTP server:

```
(host) # ping <tftphost>
```



A placeholder file with the destination filename and proper write permissions must exist on the FTP/TFTP server prior to executing the copy command.

3. Determine which partition to load the new software image. Best practices is to load the new image onto the backup partition (the non-boot partition). To view the partitions, use the show image version command.
4. Use the copy command to load the new image onto the Mobility Access Switch. The image, once copied to the stack Primary, will be pushed down to every stack member:

```
(host) # copy ftp: <tftphost> <ftpusername> <image filename> system: partition 1
```

or

```
(host) # copy tftp: <tftphost> <image filename> system: partition 1
```



When using the **copy** command to load a software image, the specified partition automatically becomes active (default boot partition) the next time the Mobility Access Switch is rebooted. There is no need to manually select the partition.

5. Execute the **show image version member all** command to verify if the new image is loaded:

```
(host) #show image version member all
```

6. Reload the entire stack:

```
(host) # reload
```

7. Execute the **show version member all** command to verify if the reload and upgrade is complete.

```
(host) #show version member all
```

8. Execute the **write memory** command to save the new configuration file header.

Upgrading from your USB using the LCD



If you are upgrading from ArubaOS 7.0.2.0 to ArubaOS 7.1.0.0 or greater, you cannot upgrade from an external USB device using the LCD screen. Use either the WebUI or the CLI to complete your upgrade.

The Mobility Access Switch is equipped with an LCD panel that displays a variety of information about the status of the Mobility Access Switch and provides a menu that allows you to do basic operations such as initial setup and reboot. The LCD panel displays two lines of text.

Use the upper right **Menu** button to navigate through LCD functions and the lower right **Enter** button to select (or enter) an LCD function. The active line, in the LCD panel, is indicated by an arrow.

Use a USB device to transfer the upgrade image:

1. Create a folder named **arubaimage** on your USB device.
2. Using your laptop, copy the new image from the support site to your USB device's folder **arubaimage**.



You must download the new image to the **arubaimage** folder or the image will not properly upload to the Mobility Access Switch.

3. Insert your USB device into the rear USB port (next to the console port) of your Mobility Access Switch.

4. Press the **Menu** button until you reach the **Maintenance** function.
5. Press the **Enter** button to enter the maintenance function.
6. Press the **Enter** button at **Upgrade Image** function.
7. Press the **Menu** button to locate the partition you want to upgrade.

```
partition 0
partition 1
```

Then press the **Enter** button to select the partition to upgrade.



Always upgrade the non-boot partition first. Upgrading the non-boot partition gives you a smoother downgrade path should it be required.

8. Press the Enter button again to confirm the partition you are upgrading (or press the Menu button to exit).

```
y: Enter button
n: Menu button
```

9. The LCD displays an a upgrade in process acknowledgement:

```
Upgrading...
```

When the upgrade is complete, the LCD displays the message:

```
Reload to boot from new image
```



When loading a software image, the specified partition automatically becomes active (default boot partition) the next time the Mobility Access Switch is rebooted. There is no need to manually select the partition.

10. From the command line, execute **show image version member all** to view the partitions:

11. Issue the following command to reload the stack:

```
(host) # reload
```

12. Execute the **show version member all** command to verify if the reload and upgrade is complete.

```
(host) #show version member all
```

13. Execute the **write memory** command to save the new configuration file header.

After completing the upgrade, your system will create a configuration file called **default.cfg.<timestamp>**. This file is your configuration at the time of upgrade. Another file called **default.cfg** is created, which is your configuration post-upgrade.

Downgrading after an Upgrade

If necessary, you can roll-back to the previous version of ArubaOS on your Mobility Access Switch using the procedure given below.

Note the following points before downgrading ArubaOS:

- Save your configuration file before and after completing your downgrade
- MSTP will be disabled upon downgrading.

Before you reboot the Mobility Access Switch with the pre-upgrade software version, you must perform the following steps:

1. Set the Mobility Access Switch to boot with the previously-saved configuration file. By default, ArubaOS creates a file called **original.cfg** upon upgrade. This file can be used instead of a previously-saved configuration file in case you did not save your configuration before upgrade.
2. Use the **dir** command to confirm your saved configuration files or **original.cfg**.

```
(host) #dir
-rw-r--r-- 1 root root 3710 Nov 7 14:35 default.cfg
-rw-r--r-- 2 root root 3658 Nov 7 14:35 default.cfg.2011-11-07_1
-rw-r--r-- 2 root root 3658 Nov 7 14:35 original.cfg
```

3. Use the boot **config-file <filename>** command to select the configuration file you will boot from after downgrading.

```
(host)#boot config-file original.cfg
```
4. Confirm that you have selected the correct file using the **show boot** command.

```
(host)#show boot
Config File: original.cfg
Boot Partition: PARTITION 0
```
5. Set the Mobility Access Switch to boot from the system partition that contains the previously running image.
6. Execute the **write memory** command after the downgrade to save your configuration

Before You Call Your Support Provider

Before you place a call to Technical Support, follow the steps listed below:

1. Provide a detailed network topology (including all the devices in the network between the user and the Mobility Access Switch with IP addresses and Interface numbers if possible).
2. Provide the Mobility Access Switch logs and output of the **show tech-support** command.
3. Provide the syslog file of the Mobility Access Switch at the time of the problem.
Best practices strongly recommends that you consider adding a syslog server if you do not already have one to capture from the Mobility Access Switch.
4. Let the support person know if this is a new or existing installation. This helps the support team to determine the troubleshooting approach, depending on whether you have:
 - an outage in a network that worked in the past
 - a network configuration that has never worked
 - a brand new installation
5. Let the support person know if there are any recent changes in your network (external to the Mobility Access Switch) or any recent changes to your Mobility Access Switch configuration.
6. If there was a configuration change, list the exact configuration steps and commands used.
7. Provide the date and time (if possible) when the problem first occurred.
8. If the problem is reproducible, list the exact steps taken to recreate the problem.
9. Provide the Mobility Access Switch site access information, if possible.

