



**Hewlett Packard**  
Enterprise

# KB.15.16.0012m Release Notes

## **Abstract**

This document contains supplemental information for the KB.15.16.0012m release.

Part Number: 5200-0165  
Published: February 2016  
Edition: 1

© Copyright 2016 Hewlett-Packard Development Company, L.P.

Confidential computer software. Valid license from HP required for possession, use or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

**Acknowledgments**

Microsoft®, Windows®, and Windows Server® are U.S. registered trademarks of the Microsoft group of companies.

# Contents

|                                     |    |
|-------------------------------------|----|
| 1 KB.15.16.0012m Release Notes..... | 7  |
| Description.....                    | 7  |
| Important information.....          | 7  |
| Version history.....                | 7  |
| Products supported.....             | 8  |
| Compatibility/interoperability..... | 8  |
| Enhancements.....                   | 9  |
| Version KB.15.16.0012m.....         | 9  |
| Version KB.15.16.0011.....          | 9  |
| Instrumentation Monitor.....        | 9  |
| Version KB.15.16.0010.....          | 9  |
| CLI.....                            | 9  |
| QoS.....                            | 9  |
| Version KB.15.16.0009.....          | 9  |
| Memory.....                         | 9  |
| Version KB.15.16.0008.....          | 9  |
| Version KB.15.16.0007.....          | 9  |
| Version KB.15.16.0006.....          | 9  |
| Configurable TLS.....               | 9  |
| Version KB.15.16.0005.....          | 10 |
| Version KB.15.16.0004.....          | 10 |
| BYOD Redirect.....                  | 10 |
| CPU.....                            | 10 |
| DHCPv4.....                         | 10 |
| DHCPv6.....                         | 10 |
| Generic Header ID.....              | 10 |
| MAC-Based VLANs.....                | 11 |
| OSPFv3.....                         | 11 |
| UDLD.....                           | 11 |
| VLAN.....                           | 11 |
| Fixes.....                          | 11 |
| Version KB.15.16.0012m.....         | 11 |
| CLI.....                            | 11 |
| Module Crash.....                   | 11 |
| OpenFlow.....                       | 12 |
| OSPF.....                           | 12 |
| PBR.....                            | 12 |
| PIM.....                            | 12 |
| QinQ.....                           | 13 |
| RIP.....                            | 13 |
| Version KB.15.16.0011.....          | 13 |
| BGP.....                            | 13 |
| BYOD.....                           | 13 |
| CLI.....                            | 13 |
| Crash.....                          | 14 |
| DHCP.....                           | 14 |
| DHCP Snooping.....                  | 14 |
| Event Log.....                      | 14 |
| File Transfer.....                  | 14 |
| IGMP.....                           | 14 |
| Logging.....                        | 14 |
| MAC Authentication.....             | 14 |

|                             |    |
|-----------------------------|----|
| Menu Interface.....         | 15 |
| MLD.....                    | 15 |
| OSPF.....                   | 15 |
| PIM.....                    | 15 |
| PIM-SM.....                 | 15 |
| Policy Based Routing.....   | 15 |
| QoS.....                    | 15 |
| RADIUS.....                 | 15 |
| RA-guard.....               | 15 |
| RMON.....                   | 15 |
| SNMP.....                   | 15 |
| Stacking.....               | 16 |
| Supportability.....         | 16 |
| Switch Initialization.....  | 16 |
| TFTP.....                   | 16 |
| VLAN.....                   | 16 |
| Version KB.15.16.0010.....  | 16 |
| Crash.....                  | 16 |
| Display Issue.....          | 16 |
| IPv6.....                   | 16 |
| OpenFlow.....               | 17 |
| OpenFlow Crash.....         | 17 |
| OSPF.....                   | 17 |
| Packet Buffers.....         | 17 |
| PIM-SM.....                 | 17 |
| PoE.....                    | 17 |
| Routing.....                | 18 |
| VLAN.....                   | 18 |
| Web GUI.....                | 18 |
| Version KB.15.16.0009.....  | 18 |
| BPDU Protection.....        | 18 |
| CLI.....                    | 18 |
| Config.....                 | 18 |
| Crash.....                  | 19 |
| DHCP Snooping.....          | 19 |
| Display Issue.....          | 19 |
| Distributed Trunking.....   | 19 |
| Event Log.....              | 19 |
| IPv6.....                   | 19 |
| Link.....                   | 20 |
| Logging.....                | 20 |
| OpenFlow.....               | 20 |
| OSPF.....                   | 20 |
| PIM.....                    | 20 |
| PoE.....                    | 20 |
| Power.....                  | 20 |
| Routing.....                | 20 |
| Security Vulnerability..... | 20 |
| sFlow.....                  | 21 |
| SFTP.....                   | 21 |
| SNMP.....                   | 21 |
| SSH.....                    | 21 |
| Stacking.....               | 21 |
| Switch Hang.....            | 21 |
| Transceivers.....           | 21 |

|                            |    |
|----------------------------|----|
| Version KB.15.16.0008..... | 21 |
| 10-GbE.....                | 21 |
| 802.1X.....                | 21 |
| Certificate Manager.....   | 22 |
| CLI.....                   | 22 |
| Command Authorization..... | 22 |
| Crash.....                 | 22 |
| Distributed Trunking.....  | 22 |
| OpenFlow.....              | 22 |
| OSPF.....                  | 23 |
| PoE.....                   | 23 |
| Port Connectivity.....     | 23 |
| QoS.....                   | 23 |
| Routing.....               | 23 |
| SSH.....                   | 23 |
| Switch Hang.....           | 23 |
| Switch Initialization..... | 23 |
| Version KB.15.16.0007..... | 23 |
| Version KB.15.16.0006..... | 24 |
| Authentication.....        | 24 |
| Certificate Manager.....   | 24 |
| CLI.....                   | 24 |
| Config.....                | 24 |
| CPU Utilization.....       | 24 |
| Crash.....                 | 24 |
| Distributed Trunking.....  | 25 |
| LLDP.....                  | 25 |
| Memory.....                | 26 |
| OSPF.....                  | 26 |
| Port Access.....           | 26 |
| QoS.....                   | 26 |
| Rate Limiting.....         | 26 |
| Self-Test.....             | 27 |
| SNMP.....                  | 27 |
| TFTP.....                  | 27 |
| Web Management.....        | 27 |
| Version KB.15.16.0005..... | 28 |
| Loop Protection.....       | 28 |
| Version KB.15.16.0004..... | 28 |
| 802.1X.....                | 28 |
| Authentication.....        | 28 |
| CLI.....                   | 28 |
| Configuration.....         | 28 |
| Counters.....              | 28 |
| Crash.....                 | 29 |
| Distributed Trunking.....  | 29 |
| File Transfer.....         | 29 |
| ICMP.....                  | 30 |
| IGMP.....                  | 30 |
| IP Phones.....             | 30 |
| IPv6.....                  | 30 |
| Latency.....               | 30 |
| Logging.....               | 30 |
| Management.....            | 30 |
| OSPF.....                  | 31 |

|   |    |
|---|----|
| PoE.....  | 31 |
| Policy Based Routing.....                         | 31 |
| Rate Limiting.....                                | 31 |
| sFlow.....  | 31 |
| SNMP.....   | 31 |
| Stacking.....                                     | 31 |
| Switch Hang.....                                  | 32 |
| Switch Initialization.....                        | 32 |
| Transceivers.....                                 | 32 |
| Web Management.....                               | 32 |
| Issues and workarounds.....                       | 32 |
| Certificate Manager.....                          | 32 |
| PoE.....  | 32 |
| Upgrade information.....                          | 32 |
| Upgrading restrictions and guidelines.....        | 32 |
| Support and other resources.....                  | 33 |
| Accessing Hewlett Packard Enterprise Support..... | 33 |
| Accessing updates.....                            | 33 |
| Hewlett Packard Enterprise security policy.....   | 34 |
| Documents.....                                    | 34 |
| Websites.....                                     | 34 |
| Customer self repair.....                         | 35 |
| Remote support.....                               | 35 |
| Documentation feedback.....                       | 35 |

# 1 KB.15.16.0012m Release Notes

## Description

This release note covers software versions for the KB.15.16 branch of the software.

Version KB.15.16.0004 was the initial release of Major version KB.15.16 software. KB.15.16.0004 includes all enhancements and fixes in the KB.15.15.0006 software, plus the additional enhancements and fixes in the KB.15.16.0004 enhancements and fixes sections of this release note.

Product series supported by this software:

- HPE 5400R Switch Series

## Important information

To avoid damage to your equipment, do not interrupt power to the switch during a software update.

## Version history

All released versions are fully supported by HPE, unless noted in the table.

| Version number | Release date | Based on      | Remarks  |
|----------------|--------------|---------------|--|
| KB.15.16.0012m | 2016-01-19   | KB.15.16.0011 | Released, fully supported, and posted on the web.  |
| KB.15.16.0011  | 2015-11-10   | KB.15.16.0010 | Released, fully supported, and posted on the web.  |
| KB.15.16.0010  | 2015-08-29   | KB.15.16.0009 | Released, fully supported, and posted on the web.  |
| KB.15.16.0009  | 2015-06-16   | KB.15.16.0008 | Released, fully supported, and posted on the web.  |
| KB.15.16.0008  | 2015-04-17   | KB.15.16.0007 | Released, fully supported, and posted on the web.  |
| KB.15.16.0007  | n/a          | KB.15.16.0006 | Never released.  |
| KB.15.16.0006  | 2015-02-06   | KB.15.16.0005 | Released, fully supported, and posted on the web.  |
| KB.15.16.0005  | 2014-11-21   | KB.15.16.0004 | Released, fully supported, and posted on the web.  |
| KB.15.16.0004  | 2014-10-30   | KB.15.15.0006 | Initial release of KB.15.16. Released, but never posted on the web.  |
| KB.15.15.0014  | 2015-08-29   | KB.15.15.0013 | Please see the KB.15.15.0014 release note for detailed information on the KB.15.15 branch. Released, fully supported, and posted on the web. |
| KB.15.15.0013  | 2015-06-16   | KB.15.15.0012 | Released, fully supported, and posted on the web.  |
| KB.15.15.0012  | 2015-04-17   | KB.15.15.0011 | Released, fully supported, and posted on the web.  |
| KB.15.15.0011  | n/a          | KB.15.15.0010 | Never released.  |

| Version number | Release date | Based on      | Remarks   |
|----------------|--------------|---------------|---|
| KB.15.15.0010  | 2015-02-06   | KB.15.15.0009 | Released, fully supported, and posted on the web.                                 |
| KB.15.15.0009  | 2015-01-07   | KB.15.15.0008 | Released, fully supported, and posted on the web.                                 |
| KB.15.15.0008  | 2014-09-15   | KB.15.15.0007 | Released, fully supported, and posted on the web                                  |
| KB.15.15.0007  | 2014-06-26   | KB.15.15.0006 | Released, fully supported, and posted on the web                                  |
| KB.15.15.0006  | 2014-03-19   | First release | Initial release of KB.15.15. Released, fully supported, but not posted to the web |

## Products supported

This release applies to the following product models:

| Product number | Description                                     |
|----------------|---|
| J9821A         | HPE 5406R z12 Switch                            |
| J9824A         | HPE 5406R-44G-PoE+/4SFP (No PSU) v2 z12 Switch  |
| J9823A         | HPE 5406R-44G-PoE+/2SFP+ (No PSU) v2 z12 Switch |
| J9868A         | HPE 5406R-8XGT/8SFP+ (No PSU) v2 z12 Switch     |
| J9822A         | HPE 5412R z12 Switch                            |
| J9826A         | HPE 5412R-92G-PoE+/4SFP (No PSU) v2 z12 Switch  |
| J9825A         | HPE 5412R-92G-PoE+/2SFP+ (No PSU) v2 z12 Switch |

## Compatibility/interoperability

The switch web agent supports the following operating system and web browser combinations:

| Operating System        | Supported Web Browsers                             |
|-------------------------|--|
| Windows XP SP3          | Internet Explorer 7, 8<br>Firefox 12               |
| Windows 7               | Internet Explorer 9, 10<br>Firefox 24<br>Chrome 30 |
| Windows 8               | Internet Explorer 9, 10<br>Firefox 24<br>Chrome 30 |
| Windows Server 2008 SP2 | Internet Explorer 8, 9<br>Firefox 24               |
| Windows Server 2012     | Internet Explorer 9, 10                            |

| Operating System | Supported Web Browsers |
|------------------|------------------------|
|                  | Firefox 24             |
| Macintosh OS     | Firefox 24             |

## Enhancements

This section lists enhancements found in the KB.15.16 branch of the software. Software enhancements are listed in reverse-chronological order, with the newest on the top of the list. Unless otherwise noted, each software version listed includes all enhancements added in earlier versions.

---

**NOTE:** The number preceding the enhancement description is used for tracking purposes.

---

### Version KB.15.16.0012m

No enhancements are included in version KB.15.16.0012m.

### Version KB.15.16.0011

#### Instrumentation Monitor

**CR\_0000164159** This feature enhances switch instrumentation and diagnostic capability.

### Version KB.15.16.0010

#### CLI

**CR\_0000171261** New CLI is introduced to enable resetting the PoE controller and restore functionality on the affected port(s): `power-over-ethernet poe-reset port <port name>`.

#### QoS

**CR\_0000172606** The Web UI can now display a port range when setting QoS, instead of displaying only the first port in the range.

### Version KB.15.16.0009

#### Memory

Enhancements were made to optimize memory usage.

### Version KB.15.16.0008

No enhancements are included in version KB.15.16.0008.

### Version KB.15.16.0007

Version KB.15.16.0007 was never released.

### Version KB.15.16.0006

#### Configurable TLS

**CR\_0000160085** Configurable TLS version and enforcing the use of a specific cipher suite.

The National Institute of Standard and Technology (NIST) has provided requirements for the use of TLS in Special Publication 800-52. These requirements state that a minimum version of TLS must be enforced, as well as the use of specific cipher suites. In order to meet these requirements,

the software has been modified to support enforcing minimum versions of TLS and specify which cipher suites are to be used.

As a TLS client, the switch will advertise the configured preferences for the TLS version and cipher suite to the server. If the server does not support the cipher suite or negotiates a lower TLS version, the connection between client and server will be terminated. As an HTTPS server, the switch will check the TLS version and cipher suite advertised by the client. Should it detect a mismatch with the configured TS version or cipher suite for the application, the connection will be terminated.

The following new CLI command has been implemented in order to configure the minimum TS version and cipher suite:

```
[no] tls application { web-ssl | openflow | syslog | tr69 | all }
lowest-version { tls1.0 | tls 1.1 | tls 1.2 | default } cipher {
aes256-sha256 | aes256-sha | aes128-sha256 | aes128-sha | des3-cbc-sha
| ecdh-rsa-aes128-gcm-sha256 }
```

The MIB HP-ICF-TLS-MIN-MIB (OID string: 1.3.6.1.4.1.11.2.14.11.5.1.112) has been implemented to provide support for the feature via SNMP.

## Version KB.15.16.0005

No enhancements are included in version KB.15.16.0005.

## Version KB.15.16.0004

### BYOD Redirect

**CR\_0000152339** BYOD redirect. The switch can now be configured for BYOD (Bring Your Own Device) redirect, which sends the device's credentials to a BYOD server such as IMC, that is configured to control network access.

### CPU

**CR\_0000124429** CPU protection during BPDU flooding. A port can receive a high volume of spanning tree BPDUs when there is a loop in the connected network. This enhancement prevents the switch CPU from being overwhelmed by limiting the rate at which those BPDUs are sent to the CPU. For more information, see the *HP Switch Software Advanced Traffic Management Guide* for your switch.

### DHCPv4

**CR\_0000128651** DHCPv4 server. The switch can now be configured as a DHCPv4 server. For more information, see the *HP Switch Software Management and Configuration Guide* for your switch.

### DHCPv6

**CR\_0000144107** DHCPv6 hardware addresses. The switch can be configured with option 79 to instruct DHCPv6 relay agents to forward client link-layer addresses. For more information, see the *HP Switch Software Management and Configuration Guide* for your switch.

**CR\_0000137520** DHCPv6 snooping and DIPLDv6. DHCPv6 snooping and Dynamic IP Lockdown for IPv6 (DIPLDv6) are now supported. For more information, see the *HP Switch Software Access Security Guide* for your switch. These features are not yet supported for YB-software switches.

### Generic Header ID

**CR\_0000144861** Generic header ID in configuration file. The switch now allows addition of a generic header ID to configuration files saved on a server. This is used for DHCP Option 67 download requests for configuration files. For more information, see the *HP Switch Software Management and Configuration Guide* for your switch.

## MAC-Based VLANs

**CR\_0000128831** MAC-Based VLANs (MBV) Enable/Disable. MBV enable/disable options are available using CLI and SNMP. For more information, see the "Web-based and MAC Authentication", and the "Port-Based and User-Based Access Control (802.1X)" chapters in the *HP Switch Software Access Security Guide* for your switch.

## OSPFv3

**CR\_0000154691** OSPFv3 trap enable/disable. The switch can be configured via CLI or SNMP to enable or disable sending of OSPFv3 traps. For more information, see the *HP Switch Software IPv6 Configuration Guide* for your switch.

## UDLD

**CR\_0000147189** UDLD Verify Before Forwarding. Unidirectional Link Detection (UDLD) has been enhanced to account for the situation when the link to the directly-connected device is up, but there is no link on one segment of the path to the remote device. For more information, see the *HP Switch Software Management and Configuration Guide* for your switch.

## VLAN

**CR\_0000145339** VLAN Precedence. Beginning with 15.06 software, if a VLAN is added to a port while authenticated clients are connected to that port, the VLAN addition is delayed until all authenticated clients are disconnected. This enhancement allows a tagged VLAN to be applied immediately to a port that has connected authenticated clients. For more information, see the *HP Switch Software Advanced Traffic Management Guide* for your switch.

## Fixes

This section lists released builds that include fixes. Software fixes are listed in reverse-chronological order, with the newest on the top of the list. Unless otherwise noted, each software version listed includes all fixes added in earlier versions.

---

**NOTE:** The number that precedes the fix description is used for tracking purposes.

---

## Version KB.15.16.0012m

### CLI

**CR\_0000157943** When the CLI command `copy command-output 'show tech all'` is executed, it is possible that the switch will run out of free memory and trigger an unexpected reboot (crash) when memory allocation fails. The risk of this problem occurring is higher when other switch tasks have consumed a large portion of free memory.

Note that the first task or process to fail to allocate memory will be the one that will be displayed in the crash message, so the event log and crash messaging may vary. One example message is as follows:

```
Software exception at svc_misc.c:858 -- in 'mCnfTrMgr', task ID =  
0xa9f7c40 -> Failed to malloc 3032 bytes
```

When insufficient resources are available to copy the requested output to a file, the process will be terminated automatically. When this happens, the following message will be displayed to the CLI and logged: The command was terminated prematurely because the output exceeded the maximum memory limit.

### Module Crash

**CR\_0000174253 Symptom:** Under certain conditions, some packets may be forwarded to the incorrect CPU queue, which could lead to a chassis module crash with an error message similar

to Software exception in kernel context at ghsException <...> Internal system error.

**Scenario:** A chassis module may crash with an error message similar to Software exception in kernel context at ghsException <...> Internal system error.

**CR\_0000182957 Symptom:** In certain conditions when hot-swapping chassis modules, the standby management module of a redundant management switch may crash with an error message indicating a Duplicate Soloist error.

**Scenario:** In a redundant switch with dual management modules, upon a chassis module hotswap, the standby management module may crash reporting an error message similar to Software exception at nsr <...>. Duplicate soloists <...>.

**Workaround:** To recover the crashed management module, perform a swap of the management module.

## OpenFlow

**CR\_0000182988 Symptom:** Incorrect meter statistics are returned to the SDN controller.

**Scenario:** Statistics meter for matching traffic to the configured traffic flows is not correctly measured when sent to the SDN controller.

## OSPF

**CR\_0000160603 Symptom:** OSPFv3 adjacency may not be successfully formed after a VLAN enabled for OSPF is reconfigured.

**Scenario:** When rate-limit unknown-unicast is configured on a port and then it is removed from the port by issuing the command `no rate-limit unknown-unicast`, the configuration is not removed properly from the switch configuration. As a result, configuring any other type of rate limiting on that port is no longer allowed due to mutual exclusivity with unknown-unicast rate limiting. The CLI will reject the new rate-limiting configuration with an error similar to <...> cannot be enabled while 'unknown-unicast' rate limiting is enabled.

**Workaround:** Disable and re-enable OSPF router functionality or perform a redundancy switchover or reboot the switch.

**CR\_0000169444 Symptom:** When MTU mismatch occurs between OSPF routers, the OSPF neighboring state is not properly restarted.

**Scenario:** When an MTU mismatch is detected on a link between two OSPF routers, with fully established adjacency, the OSPF router may maintain a FULL adjacency state without transitioning to EXSTART.

**Workaround:** Resolve the MTU mismatch between the two OSPF routers.

**CR\_0000180692** Restoring a configuration with `ip ospf <ip-addr> cost x` configuration for a loopback interface, fails with the error message `file corrupted`.

**Workaround:** Remove the OSPF configuration for the loopback interface from the configuration file before restoring it and restore the loopback interface OSPF configuration from CLI, thereafter.

## PBR

**CR\_0000181437** A PBR class with the period character '.' in the class name cannot be added to a PBR policy. The following error message is displayed: `Policy <incomplete policy name till first '.'> not found`

**Workaround:** Do not use the period character in policy or class names.

## PIM

**CR\_0000177574 Symptom:** In a PIM-SM topology with redundant path from RP to Source, when topology changes also force changes in the shortest path to Source, some of the receivers might not receive multicast streams via an existing alternate path.

**Scenario:** When a unicast routing change occurs in a PIM-SM network that triggers PIM-SM election of a new next hop PIM neighbor router via the shortest path, some receivers might not receive multicast traffic from the alternate route.

**Workaround:** Rejoin the multicast group.

## QinQ

**CR\_0000177736 Symptom:** QinQ mode is not correctly removed when the switch is restored to a non-QinQ configuration.

**Scenario:** When a switch configured for QinQ mode is restored to factory-default configuration or to a non-QinQ mode configuration file, some residual QinQ configuration will cause QinQ mode to be re-enabled.

**Workaround:** Disable QinQ mode from CLI prior to restoring the switch to another non-QinQ configuration or to factory default.

## RIP

**CR\_0000177096 Symptom:** RIP peering may not be properly established when a VLAN interface is reconfigured.

**Scenario:** After deleting a VLAN that is configured for RIP and then reconfiguring that same VLAN, RIP peers are not properly formed on that VLAN.

**Workaround:** Disable and re-enable RIP router on the VLAN interface or at the global configuration level should result in a working peering with the RIP neighbor router.

## Version KB.15.16.0011

## BGP

**CR\_0000177086** During route updates in a BGP network with Route Reflector and ECMP routes, intermittent BGP route flapping could be experienced and/or BPDUs starvation-like symptoms.

**CR\_0000178861** In a BGP topology, during link flap and/or BGP routes learning, high CPU usage could be observed and the switch could become unresponsive.

**CR\_0000182018** High CPU utilization occurs in BGP topologies if the switch obtains an invalid route as the last entry from its BGP peer.

## BYOD

**CR\_0000165412** On BYOD-redirect vlan, TCP/UDP/IP traffic is not allowed when configuring ACL permit rules and free rules are not given.

## CLI

**CR\_0000159416** Attempting to display the switch flash content consecutively from multiple sessions to the switch using the `show flash` command, while downloading an image to the switch, could cause the switch console to become unusable.

**CR\_0000174064** There is a discrepancy between the Management and Configuration Guides and implemented CLI:

The Management and Configuration Guides show `lldp config PORT-LIST dot3TlvEnable poeplus_config`.

CLI command implementation shows `lldp config PORT-LIST dot3TlvEnable poe_config`.

**Workaround:** Use the `lldp config PORT-LIST dot3TlvEnable poe_config` command syntax.

**CR\_0000180373** After removing the static-group joins and immediately adding IGMP static-group joins for the same group, the CLI routine gives an error message and the token for that group is not deleted or freed.

**Workaround:** Do not remove and immediately re-add the same IGMP static-group joins for the same group.

## Crash

**CR\_0000180705** In rare cases when attempting to configure the switch through the MENU or WEBUI interfaces or via a net management application, the switch might crash with the following signature.

```
.Active system went down: 09/10/15 12:55:32 K.15.18.0006 349 Health
Monitor: Invalid Instr Misaligned Mem Access HW Addr=0x00000000 IP=0x0
Task='mSnmpCtrl' Task ID=0xa995840 sp:0x4206ea8 lr:0x86400 msr:
0x02029200 xer: 0x00000000 cr: 0x24000400
```

**Workaround:** When configuring the switch, use only the CLI interface. Avoid using the MENU, WEBUI, or net management applications, such as IMC, to configure the switch.

**CR\_0000181774** The `show statistics policy` command might cause the switch to crash in certain configurations with maximum meters.

## DHCP

**CR\_0000170807** The switch could crash when 'display this' is applied under the dhcp-server pool configuration mode with an error message similar to `Software exception at hwBp.c:218 -- in 'fault_handler'`.

**CR\_0000180195** Fix applied to make the DHCPACK packet being sent by the DHCP Server in response to a DHCPINFROM use the MAC Address of the client as destination instead of a broadcast address.

## DHCP Snooping

**CR\_0000177144** There is a discrepancy between the DHCP-snooping binding database and the value reported by the dynamic binding counter.

## Event Log

**CR\_0000155327** Slot crashes are logged as **Warning** rather than **Major** events.

## File Transfer

**CR\_0000175506** In certain circumstances, a file transfer does not complete and causes the switch to get into the permanent `Download is in progress, you cannot reboot now!` state.

## IGMP

**CR\_0000157996** Removing and re-adding IGMP static groups could result in an `Inconsistent value` error message.

**Workaround:** After deleting the static group, wait for 3 seconds before re-adding it.

## Logging

**CR\_0000155606** IPv4 duplicate address detection log message is added to the RMON logs.

## MAC Authentication

**CR\_0000157903** With mac-auth failure-redirect feature configured as FQDN, loss of connectivity could be experienced at end points if DNS query is unable to resolve.

**CR\_0000176044** Updated Local Mac Authentication (LMA) OUIs list of Cisco IP-phones.

## Menu Interface

**CR\_0000179336** An `Invalid value` error message is received while switching from DHCP/Bootp to Manual IP address configuration via the Menu without editing the current IP address configured on a VLAN interface which already has a DHCP IP address.

## MLD

**CR\_0000135443** Node Local addresses in MLD Query/Report are not being dropped.

## OSPF

**CR\_0000174802** Negative values can be displayed for ABR and ASBR counters in the output of the `show ip route ospf` command because of an erroneous double decrement.

## PIM

**CR\_0000142977** PIM-SM allows invalid groups in Bootstrap Router (BSR) messages.

**CR\_0000152901** The CLI commands `show ip mroute` and `show ip pim mroute` on first hop router do not display the neighbor information.

**CR\_0000161990** The wrong event message, `Candidate RP functionality disabled`, is logged when PIM-DM is disabled.

## PIM-SM

**CR\_0000163279** When a PIM-SM Rendezvous Point is shutdown, the switch does not immediately send a C-RP-Adv message to the Bootstrap Router with a hold time of 0. Instead, it sends after the hold time expires.

## Policy Based Routing

**CR\_0000173164** After a loss and restoration of connectivity between the switch and the PBR specified next-hop, the switch routes traffic conforming to match rules, as well as traffic conforming to the ignoring of rules to the PBR next-hop.

## QoS

**CR\_0000175792** The `show class config` and `show policy config` commands do not display complete output when large numbers of QoS classes or policies are configured.

## RADIUS

**CR\_0000177823** During a RADIUS machine auth transition, the switch might incorrectly send the Class-ID of the user auth in the machine auth Accounting Stop packet. This results in the authentication-session of the user-auth getting cleared, so when we want to COA the client that there is no record of the session.

## RA-guard

**CR\_0000177104** The error message displayed when enabling IPv6 ra-guard on a dynamic trunk has been updated to display `IPv6 RA-guard is not supported for dynamic trunks`.

## RMON

**CR\_0000144373** When RMON alarms are enabled on the switch, unintended characters are printed in the logs of the triggered alarm.

## SNMP

**CR\_0000177848** Restoring backup configuration files with SNMPv3 enabled or QinQ SVLAN set, triggers an unexpected switch reboot even if the backup config is identical to the current config.

**CR\_0000181295** Running SNMP on `dot3StatsDuplexStatus` OID using an index of 0 causes the switch to crash.

## Stacking

**CR\_0000173162** The J number of stacked devices is not properly reported in `entPhysicalVendorType` OID.

## Supportability

**CR\_0000150068** Additional information reported in cli command `show tech buffers`.

**CR\_0000156177** Core dump files are still generated when the feature is disabled.

## Switch Initialization

**CR\_0000171369** When communicating with the switch (for example, via SCP, SSH, Telnet) over a connection with IP fragments, where some IP fragments are getting dropped, transfers stall or take an excessive amount of time.

## TFTP

**CR\_0000165110** In rare cases, transferring a file via TFTP could result in a crash because of minor leaks in RAMFS.

## VLAN

**CR\_0000169998** A port becomes an untagged member in more than one VLAN when the changes to the port's tagged/untagged VLAN membership are made in the CLI Menu.

**Workaround:** Reset the switch, reset the module, or power cycle the switch.

## Version KB.15.16.0010

### Crash

**CR\_0000170286** Inserting or removing a module results in reloading the configuration, which can lead to a switch crash with a message similar to `Software exception in ISR at btmDmaApi.c:440`.

**CR\_0000171328** When entering Fail Standalone Mode in a dual SDN controller configuration (for example, the active controller disconnected) and all the controllers are disabled, the switch might crash with a message similar to `Software exception at ovsUtil.c:4761 -- in 'mOFCtrlTask'`.

**CR\_0000174081** In some cases, a switch module may fail when a corrupted packet is detected. Messaging may be similar to `Software exception in ISR at interrupts_ahs.c:3790 -> RULES FB 8100f9f9`.

### Display Issue

**CR\_0000161014** Traffic counters that exceed the 32-bit value result in negative values in the output of CLI command `display interface PORT-NUM`.

### IPv6

**CR\_0000172573** Configuring a port for IPv6 ra-guard and adding the port to a new or existing trunk results in the generic error message `Operation failed on Port X##: General error`.

## OpenFlow

**CR\_0000172370** When a controller sends a `flow-stats` request, the switch sends a `flow stats` reply, the last header of this reply should have the flag value for `OFPMPPF_REPLY_MORE` of 0, not 1.

**CR\_0000174751** If an OpenFlow rule containing an invalid VLAN (for example, a VLAN that has been deleted) is processed, it can result in the switch or module rebooting unexpectedly (crashing).

## OpenFlow Crash

**CR\_0000163321** When an invalid meter ID is configured for an aggregate OpenFlow instance in the switch, an unexpected reboot might occur, logging a message similar to the following:  
`Software exception at inlines.h:83 -- in 'mSnmpCtrl', task ID = 0x13b11840.`

**CR\_0000163347** The switch might reboot unexpectedly (crash) while disabling and enabling a link that connects multiple Openflow controllers.

**CR\_0000169768** The switch might reboot unexpectedly (crash) while enabling OpenFlow, due to a problem computing the TCAM resources that would allow OpenFlow lookups. Crash messaging is similar to the following: `Software exception at hwBp.c:218 -- in 'fault_handler', task ID = 0x3f602380.`

**CR\_0000172055** Enabling aggregate OpenFlow instance when the controller-interface is configured to OOBM may lead to a switch crash with a message similar to `Software exception at aqTcamInterface.c:1865 -- in 'eOFNetTask'.`

**CR\_0000172595** Adding an unsupported chained group to the switch using VAN SDN controller might lead to a switch crash with a message similar to `Software exception at hwBp.c:218 -- in 'fault_handler'.`

**CR\_0000173380** When Network Optimizer is programming QOS Rules followed by an equal or higher priority rule, the switch might crash with a message similar to `Software exception at arenal_chassis_slot_sm.c:3597.`

## OSPF

**CR\_0000162013** When using CLI command `show ipv6 route` during OSPF states transition with OSPFv3 virtual link configuration, a switch crash might be encountered with a message similar to `Software exception at hwBp.c:218 -- in 'fault_handler'.`

## Packet Buffers

**CR\_0000170693** Packet buffer depletion in the switch might eventually trigger a PIM-related switch reboot (crash) similar to the following: `Software exception at PimApp.h:608 -- in 'mPim', task ID = 0xa953500 -> ASSERT0: failed.`

## PIM-SM

**CR\_0000170522** Adding a lower-numbered IPv4 subnet to an existing C-BSR VLAN makes that IP address the primary. This can cause PIM to enter an incorrect state with multicast traffic loss and generate an error message (for example, `The Candidate-BSR is already using IP address of VLAN 0`) when C-BSR configuration changes are attempted.

## PoE

**CR\_0000169265** After an electrical surge or ESD charge on a PoE port, the switch might exhibit BAD FET messages, which indicate a failure to deliver PoE on those ports. Event log messages appear similar to the following: `W 04/02/15 07:58:49 02562 ports: Port 1/1: Possible bad FET/PSE supplying PoE`

`power - suggest configuring other end of link with "no power"`

W 04/02/15 07:58:49 00567 ports: port 1/1 PD Other Fault indication.

## Routing

**CR\_0000174012** Applying BPG route-map with set weight while there is more than one path could result in switch crash with a message similar to `Software exception at bgp_med.c:597 -- in 'eRouteCtrl'`.

**Workaround:** The failure may be avoided by applying BPG route-map with set local-pref instead of using set weight.

## VLAN

**CR\_0000172434** VLAN table is not displayed in Web UI when the switch is configured with 51 or more VLANs and 60 or more active ports.

## Web GUI

**CR\_0000172729** When a VLAN is created with a name containing an apostrophe, the Web GUI troubleshooting pages appear to be blank.

## Version KB.15.16.0009

### BPDU Protection

**CR\_0000153533** If the switch receives BPDU config information with missing 'Forwarding' or 'Version' details, it incorrectly treats the message as a valid BPDU, resulting in spanning tree instability.

### CLI

**CR\_0000157943** When the CLI command `copy command-output 'show tech all'` is executed, it is possible for the switch to run out of free memory and trigger an unexpected reboot (crash) when memory allocation fails. Conditions that increase the risk of this problem are the production of a file larger than 70 MB, or execution of the command when other switch tasks have consumed a large portion of free memory. Note that the first task or process to fail to allocate memory will be the one that is displayed in the crash message, so the event log and crash messaging may vary. One example message is as follows: `Software exception at svc_misc.c:858 -- in 'mCnfTrMgr', task ID = 0xa9f7c40 -> Failed to malloc 3032 bytes.` When insufficient resources are available to copy the requested output to a file, the process is terminated automatically. When this happens, the following message is displayed to the CLI and logged: `The command was terminated prematurely because the output exceeded the maximum memory limit.`

**CR\_0000159271** In some configuration contexts (for example, ip-access list, vlan), the IPv4 CLI commands (such as IP source-lockdown) are actually configuring the feature for IPv6.

**CR\_0000161010** When the `display` command is executed with pim-dense mode enabled, the command output/configuration is not displayed correctly.

**CR\_0000172046** The commands `show lldp info local-device` and `show lldp info remote-device` sometimes fail to display the correct information when the switch is not connected to any remote device.

## Config

**CR\_0000170324** When a change is made from the CLI in the **Switch Configuration – Port/Trunk Settings** menu, the change is not saved, resulting in an `Unable to save field error`.

## Crash

**CR\_0000164064** When a free radius authenticated user attempts to HTTPS to the switch web management GUI of the 2530-24G, the switch crashes with Health Monitor: Read Error Restr Mem Access Task='tHttpd'.

**CR\_0000165111** When OSPFv3 is enabled with traps, the SWS TA stack crashes the commander with a message similar to Software exception at hwBp.c:218 -- in 'fault\_handler', task ID = 0x3c402380.

**CR\_0000166340** An SNMP crash occurs during PCM discovery on 2620 and 2650, if an Avaya phone is connected to the switch that advertises an organizational OUI value 00-00-00 (all zeros), or any neighbor entry contains an all zero OUI type TLV, during walkmib on the switch.

**Workaround:** Change the **lldp admin** status to **txOnly** on the link that is connected to the specific Avaya phone.

**CR\_0000168119** Switch may crash in an unknown state over a very long period when a rare set of Web operations occur.

**CR\_0000168194** The switch might restart with an error message similar to the following during a session logout, kill, or timeout: Software exception crash at multMgmtUtil.c:151 -- in 'mOobmCtrl', task ID = 0x13b15e00-> Internal error.

## DHCP Snooping

**CR\_0000160884** When DHCP-snooping is enabled, if any ports are configured as untrusted, DHCP packets are sent to those ports.

## Display Issue

**CR\_0000167906** When the alert log is sorted by date/time, items are sorted (erroneously) alphabetically by day of the week, rather than day of the month.

## Distributed Trunking

**CR\_0000168368** When the Distributed Trunk link is lost between the DTS primary switch and a distributed trunk device (DTD), the communication between the DTS primary and a distributed trunk device (DTD) or any hosts of DTD are also lost. This issue also causes loss of communication between DTD local hosts and any destinations whose path is the DTS-primary. Communication issues remain until the DT link is back online, AND, the other DT-link is disabled/re-enabled.

## Event Log

**CR\_0000171023** During incorrect login attempts, a message is only logged to the event log after 3 attempts. A change has been made to log incorrect username/password attempt after *each* occurrence.

## IPv6

**CR\_0000167682** The security feature "IP Source Lockdown" is not operating correctly and disrupts IPv6 traffic. This same feature can't be consistently and reliably disabled as expected. This CR includes two issues:

1. IPv4 ip source-lockdown on a port blocks IPv6 traffic in VLANs that do not have IPv4 DSNOOP enabled.
2. When removing the configuration by disabling 'no ip source-lockdown' globally and then removing the feature from the ports 'no ip source-lockdown 11.13', the feature does not seem to be removed correctly and keeps blocking IPv6 traffic.

This issue occurs when both DIPLD and DIPLDv6 are enabled.

## Link

**CR\_0000169819** When the switch is configured for Rapid-PVST (RPVST), any changes to port path cost takes effect properly. However, when the port is disabled and then re-enabled, the port path cost applied and also advertised to neighbors changes to the default path cost.

## Logging

**CR\_0000155070** The Alert-Log filter criteria does not work as expected when a substring is used as a filter.

**CR\_0000171737** After logging in to the switch using Operator credentials, and the enable command is then executed with incorrect Manager credentials, the event log erroneously shows the session belonged to Manager username.

**CR\_0000172072** Event log `show log -r` does not show an invalid key attempt during an SSH Public Key Login Failure.

## OpenFlow

**CR\_0000170688** When enabling HPE NetworkProtector on the VAN SDN Controller, the switch loses packet buffers until they are depleted and eventually the switch stops functioning and loses management access.

## OSPF

**CR\_0000161636** When OSPF v3 is used, incorrect route calculations on the ABR by the switch result in symptoms such as multiple routes in RIB, and incorrect route selections based on preference settings (in the case of cost and distance, the lower value is preferred). Rebooting the ASBR may temporarily resolve the issue.

## PIM

**CR\_0000169557** Under certain conditions, an IGMP stream freezes for all in the group. Two examples known to cause this are:

1. When a client directly attached to Core 1 sends a LEAVE for a Group that it is streaming, all other clients watching that Group freeze, until either a GQ is sent out for that Group, or another client sends a new Join for that group, after which all other clients resume streaming that group again.
2. When there are clients directly attached to Core 2, the LAST leave causes clients directly connected to Core 1 to freeze.

## PoE

**CR\_0000155592** A PoE fault occurs after removing power supplies. The switch drops power across the board for about 30 seconds. This version contains a firmware fix to resolve this issue.

## Power

**CR\_0000150101** The value for the Total Power displayed using the `show system power-supply` may be incorrect if one PSU in a multiple PSU system has its AC cord removed.

## Routing

**CR\_0000160131** When more than 10,000 RIP routes are distributed by a neighbor, this RIP peer does not learn all of the routes – learning “stops” after about 10,000 neighbor RIP routes are installed.

## Security Vulnerability

**CR\_0000162428** If the CLI command `verify signature flash [primary] or [secondary]` is issued more than once, it shows inconsistent results though the signature has already been verified.

**CR\_0000166717** Login is permitted with the default username Manager, even when the Manager username has been changed to a custom username.

## sFlow

**CR\_0000168606** Switch 5400R continues to send incorrect sFlow datagrams for non-existent ports after removing the module associated with these ports.

## SFTP

**CR\_0000162987** Management modules go out of synchronization and fail to recover when large SFTP copies or a large number of SFTP copies are performed.

## SNMP

**CR\_0000158713** When reading the MIB data for a PSU Product ID J number, the number displayed is truncated by one character.

## SSH

**CR\_0000171834** When logging in using Operator credentials for SSH and then executing the enable command with Manager credentials, the user name in the event log does not show the Manager username; it shows Operator mode.

## Stacking

**CR\_0000170433** In a stacked configuration, if the MAC Authentication password is set to a password of exactly 16 characters (max length) and configuration is saved, when the stack reboots, the member switch hangs during reboot.

## Switch Hang

**CR\_0000167470** A software exception occurs similar to: `Software exception at _chassis_slot_sm.c:3810 -- in 'eChassMgr', task ID = 0x3c93f100^J-> Member halting - non-conduit slave (Ports 1/1-24,49-50) lost comm (4).^J Debug slave and master.^J`". This occurs during an arp-age timeout when heartbeat packets are failing to the master. It can occur when a high priority packet is sent to router's mac address.

## Transceivers

**CR\_0000163290** Some SR J9150A and LRM J9152A transceivers show as NON-HP with K.15.07 and W.15.07 software.

## Version KB.15.16.0008

### 10-GbE

**CR\_0000153118** When a 10G port is reset or when the port speed switches from 10 Gbps to 1 Gbps, or vice versa, the port might start dropping packets, flood packets, or packets received on the port might be corrupted. The latter condition might eventually cause the module or stack member to crash with a message similar to the following: `Software exception in ISR at interrupts_ahs.c:4087 -> Too many HPP ints: 00040000`. This problem affects only 10G Ethernet ports on 3800 series switches and ports 1, 2, 4, 7, and 8 on the J9546A and J9546A version 2 modules.

### 802.1X

**CR\_0000164489** 802.1X re-authentication period works if the client connects after the switch is booted. If, however, the switch reboots while clients are connected, it authenticates initially, but no re-authentication occurs.

## Certificate Manager

**CR\_0000162594** When a TA certificate is present during boot up, the switch may hang/restart with the following error: Software exception at certmgr\_store.c:1921 -- in 'swInitTask. Triggered when a corrupted certificate is present as TA certificate upon boot up. The system tries to double free and hangs.

**CR\_0000164093** When an IDEVID certificate is being used to establish TLS connections with a CNM server, the existing signature algorithm is updated from SHA-1 to DER, with new root certificate for the RA server.

## CLI

**CR\_0000159808** When DHCPv6 Snooping is enabled and the switch has recorded a binding on a trunk, the output of the CLI command `show dhcpv6-snooping binding` displays the trunk ID as a + sign when the trunk ID exceeds four characters. For example, when a binding was learned on Trk11:

```
MAC Address IPv6-Address VLAN Port Time Left
-----
f0921c-2312c0 2001::82 1 + 5565
```

## Command Authorization

**CR\_0000160066** The `listen-port help` command has changed:

Usage: [no] `listen-port <PORT-NUM>`

Description: Specify TCP the port on which the OpenFlow agent of the switch waits (listens) for incoming connections from an OpenFlow controller. The default port number is 6633.

The Description should be changed to read: Description: Specify the TCP port on which the OpenFlow agent of the switch listens for incoming connections from an OpenFlow controller. The default port number is 6633.

## Crash

**CR\_0000170037** When a minimum TLS cipher suite version is enforced and a client negotiates a cipher suite, the switch might crash due to a watchdog timer expiry. The crash message may be similar to the following: Software exception at bsp\_interrupts.c:90 -- in 'fault\_handler'.

## Distributed Trunking

**CR\_0000165004** When Spanning Tree is enabled and the switch is rebooted, after the reboot the DT peer-keepalive port is set to a Spanning Tree 'blocking' state (alternate/discarding). This state prevents the transmission and reception of Distributed Trunking peer-keepalive packets. When the peer-keepalive port is toggled, the port transitions to a correct Spanning Tree Designated/Forwarding state and the peer-keepalive packets is sent and received again.

## OpenFlow

**CR\_0000162736** When adding a rule entry to OpenFlow, a `TABLE_FULL ECodeFlowModeFailed` error can occur, even when there is space for additional rules.

**CR\_0000163370** Violation of OpenFlow requirement that if the match field `OXM_OF_IP_DSCP` is used, the `ETH TYPE` must be `0x0800` or `0x86dd`.

**CR\_0000164665** 3500 OpenFlow does not forward `NORMAL` with `HTTP` when `COPY` and `NORMAL` are included in an Action Set Flow. `HTTP GET` requests might be lost once `COPY` and `NORMAL` are set in an Action Set Flow. `HTTP GET` requests are blocked once `COPY` and `NORMAL` are set in an Action Set Flow. 3500/6200

## OSPF

**CR\_0000160228** During display of the output from two CLI commands, `display ospf routing` or `display ospf lsdb`, when a lot of routes are configured, if you use CTRL + C to interrupt the output, the console can hang for up to three minutes.

## PoE

**CR\_0000146605** All the ports on a module fail to deliver power when a single controller fails.

## Port Connectivity

**CR\_0000161856** If `ip igmp static-group <group-address>` is added to the switch configuration for any VLAN, then upon a warm or cold reboot of the switch, the switch does not establish a link on any Ethernet ports. This issue is also present on stand-alone 2920, with stacking disabled.

## QoS

**CR\_0000162179** When attempting to remove a configuration line from a QoS policy, the switch returns `commit failed`. The customer cannot delete the line and has to reload the configuration to recover. Occurs when multiple policies are configured.

## Routing

**CR\_0000164381** When multiple ECMP routes are used with BGP, MSTP and VRRP, issues resulted due to message queues becoming full.

## SSH

**CR\_0000159714** The output of the `display device` command over SSH displays incorrectly as a misaligned single line of output, due to no carriage returns between multiple lines. This occurs more frequently if the terminal width is set > 80 characters, when SSH senses the terminal settings on Login.

**CR\_0000165393** When the SSH client has a keepalive mechanism configured that requires a response from the SSH server on the switch, the SSH client terminates the session after the first keepalive packet is transmitted. This happens because the switch drops the client's keepalive packet due to an incorrect packet length calculation. This issue has been observed using an openSSH client with the `ServerAliveInterval` configured and the parameter `'want_reply'` enabled.

## Switch Hang

**CR\_0000166649** A PIM router might hang when RPF Override is enabled or disabled and another PIM-related CLI command is entered that changes the PIM protocol configuration. This is caused by the `'rpf-override'` code locking the PIM code, but not releasing it when it has finished.

## Switch Initialization

**CR\_0000162540** Switch hangs when downgraded to a previous version when mac classes and policy are configured.

This is a release note for both KB.15.16 and KB.15.15. (cycle 4).

## Version KB.15.16.0007

Version KB.15.16.0007 was never released.

## Authentication

**CR\_0000156072** When generating a self-signed certificate or Certificate Sign Request (CSR) in the web interface, the software incorrectly allows the use of non-ASN1 characters. When the CLI is used, the action is not allowed and an error message is displayed.

## Certificate Manager

**CR\_0000159204** When a self-signed certificate is generated on the CLI, the certificate does not contain a valid start and end-date. This causes the certificate to be invalid, which causes problems establishing HTTPS sessions or using syslog over TLS. When the self-signed certificate is generated in the web interface, this problem does not occur.

## CLI

**CR\_0000154706** When a user configures a blackhole route for an IPv4 or IPv6 address and then attempts to configure that same IP address as a VRRP virtual IP address, the invalid configuration is rejected with the error message `Cannot configure a reject/blackhole route as backup virtual-ip-address`. When the configuration order is reversed by first configuring the IP address as VRRP virtual IP address and then the blackhole route, the configuration is incorrectly permitted by the configuration parser.

**CR\_0000156237** When a user has enabled Spanning Tree on the CLI and configured a protocol version other than the default MSTP, the CLI Menu does not allow the user to modify Spanning Tree parameters. The menu indicates that the switch requires a reboot. When the switch is actually rebooted, the same problem is present after the reboot.

**CR\_0000161668** After a user has changed the Spanning Tree Protocol Version to RPVST in the CLI Menu, the switch prompts the user to save the configuration and reboot the system to activate the changes. However, after saving and rebooting, those messages continue to be displayed.

## Config

**CR\_0000145221** When a user enables Meshing, the software prompts the user to save the configuration and reboot the system. However, after saving the configuration, issuing the command to reboot the system causes the software to issue the following redundant message: `Do you want to save current configuration [y/n/^C]?`

## CPU Utilization

**CR\_0000158909** When the CLI command `show system chassislocate member <ID>` is issued on a stack of switches, the CPU utilization rises to 100%.

## Crash

**CR\_0000149153** When an exceptionally large amount of IP Address Manager (IPAM) output is generated by the output of `show tech all` and captured using the `copy command-output CLI` command, the system may crash with the following message:

```
NMI event SW:IP=0x00147168 MSR:0x02029200 LR:0x00120f7c
cr: 0x44000400 sp:0x04d60f30 xer:0x00000000
Task='mSess3' Task ID=0x4d59728
```

**CR\_0000152463** When the syslog feature **logging notify running-config-change** is enabled, inserting a new module into the chassis or reloading a module can cause the system to run out of message buffers. Once the message buffer pool is depleted, the system crashes with the typical `no msg buffer` or `no resources available` crash messages. For example:

```
Software exception at alloc_free.c:533 -- in 'mChassCtrl', task ID = 0xa99f140
-> No msg buffer
Software exception in ISR at btmDmaApi.c:436
-> ASSERT: No resources available!
```

**CR\_0000155066** The switch may reboot unexpectedly with a Software Exception message similar to: `Software exception at stackingFile.c:2224 -- in 'mStackDatWriter', task ID = 0x3c953b00 -> Internal Error ID: 6382d706` when a lot of TFTP file transfers to an external TFTP server have occurred.

**CR\_0000159125** When a system has Distributed Trunking enabled, a crash might occur when a packet with an incorrect flag is received on the ISC port. Instead of dropping the packet, the software attempts to process the packet, which triggers a crash similar to the following: `Health Monitor: Invalid Instr Misaligned Mem Access HW Addr=0x0065d2f8 IP=0x65d2f8 Task='tDevPollTx' Task ID=0xa9f9700 sp:0x2ecc828 lr:0x6081c0 msr: 0x02029200 xer: 0x20000000 cr: 0x48000800.`

**CR\_0000159646** After enabling Control Plane Protection on a system that contains a module or stack member switch that has less than 24 ports, all modules in a chassis or all stack member switches crash repeatedly with the following message: `Software exception at aqTcamSlaveUtils.c:2056 -- in 'mAsicUpd', task ID = 0x1b1e6780 -> Policy Engine: Port instance not on this slot.`

**CR\_0000159764** Due to a semaphore deadlock, a switch might crash with a message similar to the following: `NMI event HW:IP=0x0151dec4 MSR:0x02029200 LR:0x0151e468 cr: 0x20000800 sp:0x02f01460 xer:0x20000000 Task='tDevPollRx' Task ID=0xaa28000.`

**CR\_0000159784** The device might hang when configuring an IPv6 static route and configuring the forwarding address as a virtual-IP-address.

**CR\_0000162148** When an OSPFv3 NSSA area is changed to a stub area, the switch might reboot unexpectedly with a message similar to the following: `ospf3_ls.c:3748 -- in 'eRouteCtrl', task ID = 0xa9e7080-> Routing Stack: Assert Failed.`

**CR\_0000162155** Configuring an OpenFlow instance using secure mode, enabling OpenFlow, and then configuring the lowest-version for OpenFlow may cause the switch to reboot unexpectedly. Other triggers include updating the `tls` lowest-version for an app for which a cipher is already configured, and executing the `no tls app <app> lowest-version <ver> cipher` CLI command. The crash message references a mem-watch trigger.

**CR\_0000162400** When the switch continuously attempts to transfer a file to a destination that returns an error (for example, because it ran out of space to store the file), the switch might eventually crash with the following message: `Software exception at hwBp.c:218 -- in 'fault_handler', task ID = 0x3c403380 -> MemWatch Trigger: Offending task 'mftTask'.`

## Distributed Trunking

**CR\_0000157975** When VRRP is enabled on a DT switch that is in VRRP Master State for one or more VLANs, deleting the VLANs by issuing the command `no vlan <vlan ID>` does not clear a VRRP data structure correctly. This causes the DT switch to assume it is still the owner of the VRRP virtual MAC addresses and ignore any learn updates it receives from its DT peer switches for those MAC addresses. This, in turn, can cause the VRRP virtual MAC addresses to get stuck on the system's ISC port.

## LLDP

**CR\_0000157298** When a PD sends an LLDP-MED TLV to a switch port in which the PD uses the invalid value of 0 Watts, the switch software actually applies the invalid 0 Watts. This causes the PD to reboot every time it transmits the 0 Watts in the TLV. The switch might log overcurrent warnings (`00562 ports: port <port ID> PD Overcurrent indication`) because the PD is already drawing power over the port when the software applies 0 Watts power. The value of 0 Watts in the TLV will henceforth be rejected with the error `Invalid power value 0 deciWatts received from MED PD on port <port ID>.`

## Memory

**CR\_0000150414** After a Flare OpenFlow controller sent flow modification packets to a switch that contained invalid zero-length action headers, the switch became unresponsive and eventually crashed with the following message:

```
NMI event SW:IP=0x09f4e6ec MSR:0x02029200 LR:0x09f4efe4
cr: 0x88000800 sp:0x130ad738 xer:0x20000000
Task='eOFNetTask' Task ID=0x130add28
```

**CR\_0000152126** Every time a user issues the command `terminal width` or `terminal length`, 40 bytes are allocated in memory that are never freed.

**CR\_0000153262** SNMP Informs that are not acknowledged by the inform receiver are not properly removed. Over time, the amount of SNMP Inform messages stored in memory increases to the extent that insufficient contiguous memory is available to other processes, which causes the system to crash.

## OSPF

**CR\_0000155425** When a high volume of Link State Acknowledgements are flooded to an OSPFv2 neighbor the adjacency might go down because OSPF Hello packets are dropped.

**CR\_0000160538** When a redundancy failover is executed on an OSPFv2 router that has Graceful Restart enabled, one or more neighbors might crash with the following message: `Software exception at ospf2_ls.c:1839 -- in 'eRouteCtrl', task ID = 0xa91ff00 -> Routing Stack: Assert Failed.`

**CR\_0000160814** When a user reconfigures an OSPFv3 area from stub or normal to NSSA without rebooting the router or restarting the OSPFv3 protocol, the ASBR status is not updated on the OSPFv3 router when it becomes an NSSA ABR. Likewise, when the area is reconfigured from NSSA to stub or normal, the ASBR status is also not updated and the router continues to act as if it is still an ASBR. Due to the incorrect ASBR status, the route advertisements are not correct, which results in routes being installed on routers in an area when they should not be or routes not being advertised when they should be.

**CR\_0000161927** When the redistribution of static or connected routes on an NSSA OSPFv3 router is disabled, the ASBR flag is not correctly reset. This can cause the router to function as an ASBR router when it should not.

## Port Access

**CR\_0000158890** After disabling and re-enabling a port, the port may end up in a state where it has established link, but does not pass any traffic. This issue can occur only on systems that do not have MSTP enabled.

## QoS

**CR\_0000159713** The Queue Monitor feature was inadvertently not enabled on the 5400R switches. The Queue Monitor allows the user to monitor the different ports queues and display the amount of dropped packets in each queue. The following CLI command enables the feature: `[no] qos watch-queue <port>`. The command `show qos watch-queue [port]` displays the number of dropped packets per port queue.

## Rate Limiting

**CR\_0000163326** The guaranteed minimum bandwidth (GMB) feature and new feature Egress queue rate-limit are concurrent features. According to the design, we should not be able to configure Queue rate-limit values less than the GMB for each queue. This behavior is by design, but a special case was added to the software to allow a 0% rate-limit queue value in order to disable the feature.

**CR\_0000163327** A warning message designed for trunks is seen even if the user misconfigures the Egress Queue Rate-limit feature.

**CR\_0000163336** A configured rate-limit of 100% per queue is shown in the running config for 4-queue and 2-queue scenarios, but not in an 8-queue configuration.

**CR\_0000163745** Redundancy switchover on a switch impacts the default Guaranteed Minimum Bandwidth (GMB) implementation in 2-queue and 4-queue configurations.

**CR\_0000163748** When a new Queue Rate-limit configuration is saved on the 5400R zl series switch, the new configuration does not take effect when a redundancy switchover occurs. It does take effect when the switch is booted.

**CR\_0000163828** Traffic flow on lower-priority queues does not match the rate-limit queues configuration.

**CR\_0000163829** There is inconsistent CLI output in response to the `show rate-limit queues <port>` and the `show rate-limit queues` CLI commands when rate-limit queues are configured on a port and then the port is added to a trunk interface.

**CR\_0000163861** When the rate-limit configuration is removed from a trunk port using the `no rate-limit queues out` CLI command, the change does not take effect until a system boot occurs. Edits to the rate-limit occur immediately.

**CR\_0000163864** Rate-limit queue configuration of 100% for Queue 1 and 0% for other queues does not work as intended.

**CR\_0000163995** The switch allows configuration of rate-limit queues that are less than Guaranteed Minimum Bandwidth (GMB) profile for the same queue in a strict queuing scenario. The switch should not allow the rate limit to be less than the minimum bandwidth setting for any queue.

## Self-Test

**CR\_0000161371** When the switch is booting, the Out-of-band-management (OOBM) port might fail to initialize during self-test, resulting in the following message: `Switch Chassis needs replacement at scheduled downtime`. Note that this is a software error and not a genuine hardware failure.

## SNMP

**CR\_0000156209** When a configuration file is downloaded to the switch in which the SNMP community name string for unrestricted access is something other than `unrestricted`, the software resets the access-level to the default `restricted`. Although it is expected behavior to default to `restricted` when the string `unrestricted` is not precisely matched, the software has been modified to allow the use of both lower and uppercase characters in the word `unrestricted` when parsing a downloaded configuration file.

**CR\_0000160352** The string value for the temperature sensor's instance of the object `entPhysicalName (.1.3.6.1.2.1.47.1.1.1.1.7)` is incorrectly set to `Chassis`. It should return `Chassis Temperature`.

## TFTP

**CR\_0000159058** When the switch is used as TFTP server and configuration files are transferred from the switch to an external TFTP client, the software creates a temporary file in memory that is removed after the transfer has completed. However, the temporary file is not deleted when an error occurs during the file transfer. When repeated transfers of configuration files fail, the temporary files accumulate and might deplete the available memory space. Once depleted, further file transfers fail and the switch might reboot unexpectedly (crash). Note that when the switch is rebooted, all temporary files are removed from memory.

## Web Management

**CR\_0000160654** When 51 or more VLANs are configured on the switch, the web interface does not display any VLAN under the **VLAN Management** and **Multicast IGMP** tabs.

## Version KB.15.16.0005

### Loop Protection

**CR\_0000160268** When there is a downstream network loop, the switch can learn its own port MAC address and add it to the MAC table. Normally the switch does not learn its own port MAC addresses, so this is incorrect behavior. However, this does not impact the Loop Protection feature as originally thought. Loop Protection works properly even with this incorrect MAC learning issue.

## Version KB.15.16.0004

### 802.1X

**CR\_0000149780** Already-authenticated clients that send an EAPOL-Start message are de-authenticated by the switch. This situation happens if the client runs Windows Vista and later operating systems that are set to "include learning".

### Authentication

**CR\_0000148832** A switch configured with RADIUS authentication for primary login, and local authentication for secondary login fails to use local authentication when RADIUS servers do not respond. In that situation, the switch console is not accessible to valid users.

### CLI

**CR\_0000136134** After issuing the command `no ip ssh cipher cipher_option`, the entry is listed twice in the output of `show run`.

**CR\_0000145136** When the switch is configured with the `console event critical` setting, the event log output of `show tech all` lists only the critical events. With this fix, `show tech all` lists all event log entries.

**CR\_0000145812** A new command `tcp-push-preserve` is added. This command is enabled by default, and causes TCP packets with the "push" flag to be sent before other packets in the queue. Note that high concentrations of TCP packets with push flags under certain conditions can destabilize your network. Use the `no` form of this command to disable the feature.

**CR\_0000148661** When the output of `show power-over-ethernet brief` displays a Detection Status of either `Searching` or `Delivering for a port`, the `show tech all "poe_status_port all"` section displays `Other Fault` as the "Detect Stat".

**CR\_0000150144** The output of `show dhcp-relay bootp-gateway vlan VLAN_number` gives an incorrect BOOTP Gateway address for VLANs that are not configured for DHCP relay.

**CR\_0000152440** The output of `show tech all` halts while displaying `lmaDbUtiltraverseLmaProfTbl`, with the message `=== The command has completed with errors. ===`.

### Configuration

**CR\_0000152757** After configuring `snmp-server host` on the Commander, stack member configuration files include two lines with SNMPv3 configuration.

### Counters

**CR\_0000149229** The "Route changes" counter in the output of `show ip rip` increments with every RIP update the router receives, even if there are no route changes.

**CR\_0000151412** The output of a query for meter statistics gives an incorrect value for OpenFlow meter duration.

**CR\_0000151415** The output of a query for port statistics gives an incorrect value for OpenFlow statistics duration.

## Crash

**CR\_0000146176** After receiving multiple route changes or route flaps in a short period of time, the switch might reboot unexpectedly with a message similar to Software exception at `krt.c:2134 -- in 'eRouteCtrl'`, task ID = 0xa9bc400 -> Routing Stack: Assert Failed.

**CR\_0000151102** In a rare situation, after a failover to the Standby Management Module (SMM) or the stack's Standby switch, the switch might reboot unexpectedly with a message similar to Software exception at `asicMgrSlaveFilters.c:185 -- in 'mNSA'`, task ID = 0x1b1fea80 -> Internal Name Server Error.

**CR\_0000153386** When a large number of 802.1X clients are being authenticated, reconfiguring port security modes such as “learn-mode” might cause the switch to reboot unexpectedly with a message similar to Software exception at `multMgmtUtil.c:88 -- in 'mPpmgrCtrl'`, task ID = 0x13b1f940 -> Internal error.

**CR\_0000153700** Three commands are removed from the `show tech all` and `show tech route` commands (which invoke many sub-commands): `show ipv6 ospf3 link-state link-scope detail`, `show ipv6 ospf3 link-state area-scope detail`, and `show ipv6 ospf3 link-state as-scope detail`. In certain situations, issuing those commands will cause the switch to reboot unexpectedly with a message similar to Health Monitor: Invalid Instr Misaligned Mem Access HW Addr=0x017cb590 IP=0x17cb590 Task='eRouteCtrl' Task ID=0xa96de00 sp:0x48cea20 lr:0x10086d4 msr: 0x02029200 xer: 0x20000000 cr: 0x44000400.

**CR\_0000154053** When the switch has 802.1X-authenticated clients on a VLAN and the user deletes that VLAN, the switch might reboot unexpectedly with a message similar to Software exception at `multMgmtUtil.c:151 -- in 'eChassMgr'`, task ID = 0x3c945800 -> Internal error

**CR\_0000154769** With a static IGMP group configured, after issuing the `show run` command, changing the sFlow configuration might cause the switch to reboot unexpectedly with a message similar to Health Monitor: Restr Mem Access HW Addr=0x60630015 IP=0x1045630 Task='mSnmpCtrl' Task ID=0xa98b4c0 sp:0x47ecc50 lr:0x104a0ac msr: 0x02029200 xer: 0x20000000 cr: 0x48000400.

## Distributed Trunking

**CR\_0000148165** When VRRP routers have distributed trunking enabled, VRRP failovers might cause the VRRP virtual MAC addresses (and therefore remote subnets) to become unreachable.

**CR\_0000148170** A MAC address that is learned by a distributed trunking switch and then moved to another port might be listed on the wrong port by the peer distributed trunking switch, causing that MAC address to be unreachable from the peer switch.

**CR\_0000149160** After removing the Inter-Switch Connection (ISC) and reconfiguring it, some traffic might be dropped or switched to the wrong port.

**CR\_0000151202** After receiving a join on an Inter-Switch Connection (ISC) port, the switch does not forward joins from other ports onto the ISC.

## File Transfer

**CR\_0000145212** Software downloads via SSL fail with certain browsers, including Internet Explorer versions 7, 8, and 10.

**CR\_0000148584** A configuration file with a blank community name in the `snmp-server host` entry cannot be downloaded to the switch. Although the switch does not allow the `snmp-server host` entry to be configured with a blank community name, earlier software bugs might cause this condition.

## ICMP

**CR\_0000155702** The switch sends a ping request to a random IP address every 20 minutes.

## IGMP

**CR\_0000128678** In certain topologies the IGMPv2 "Leave Group" from one host can cause the multicast stream to be dropped, even though there are other hosts receiving that stream.

## IP Phones

**CR\_0000137652** An IP phone that uses the "Automatic Port Synchronization" feature loses its IP address and possibly drops the current call. This has been observed when the switch is configured with the command `cdp mode pre-standard-voice`, and the PC to which the phone is connected goes into hibernation. In that situation the "Automatic Port Synchronization" feature causes the phone to drop and then re-establish link with the switch.

**CR\_0000147849** Alcatel phones might reboot unexpectedly when connected to a switch configured to use MAC authentication for IP phones and to use 802.1X authentication for PCs.

## IPv6

**CR\_0000148594** IPv6 router advertisements that indicate an off-link prefix are not set as "preferred" in the switch, which causes incorrect information in the output of `show ipv6`, and can affect connectivity to hosts that use IPv6 Stateless Address Autoconfiguration. This issue also causes the sFlow "Agent Address" to be listed as 0.0.0.0.

## Latency

**CR\_0000129743** When the switch receives a high volume of traffic for unknown destinations, the resulting ARPs sent by the switch in combination with other incoming traffic the switch must process can cause latency and dropped packets. In this situation, the event log might report `IpAddrMgr: IPAM Control task delayed due to slave message queues too full`.

## Logging

**CR\_0000146773** In an IPv4 plus IPv6 environment, upon switch bootup the event log displays the set of source IP policy ("srcip") messages twice. With this fix, IPv6 policy messages are distinguished from IPv4 policy messages.

**CR\_0000147833** Some RMON events are not correctly defined for VRRP, which causes the switch to report an error such as `system: Unknown Event ID 776` when those events occur.

**CR\_0000149891** When a user disables layer 3 on a VLAN, the event log message might state that layer 3 was disabled for the wrong VLAN.

**CR\_0000150244** Some RMON events are not correctly defined for fault-finder (FFI), SSL, and virus throttling, which causes the switch to report an error such as `system: Unknown Event ID 776` when those events occur.

## Management

**CR\_0000149528** In some situations with multiple TELNET and/or SSH sessions established, the switch does not accept additional management sessions even if some of the existing ones are killed, responding with the message `Sorry, the maximum number of sessions are active. Try again later`.

**CR\_0000155717** After disabling the Out of Band Management (OOBM) interface, saving the config and rebooting the switch, the OOBM interface does not come up even after it is re-enabled.

## OSPF

**CR\_0000147711** Link State Advertisements (LSAs) are retransmitted by the router before the retransmit timer expires. This improves the original OSPF fix (CR\_0000134463).

**CR\_0000149413** The SPF counter for OSPFv3 increments for link-state updates even if there is no topology change.

**CR\_0000155308** When a large number of routes (on the order of 9000) are updated with a better path, the better paths are not always put into the routing table, which can cause unreachable subnets.

## PoE

**CR\_0000148808** After disabling PoE on one or more ports, the output of `show cpu slot <slot-number>` shows an increase in CPU utilization of 15% or more.

**CR\_0000155619** Some Unify IP phones exhibit a PoE incompatibility with some HPE switches, which might result in a hard failure of the phone. For more information see the customer advisory at <http://h20564.www2.hp.com/hpsc/doc/public/display?docId=c04438506>.

## Policy Based Routing

**CR\_0000147703** In some situations, the switch does not allow a `service-policy` to be removed from a VLAN, responding with the error `commit failed`.

**Workaround:** Reboot the switch, then issue the `no service-policy` command.

## Rate Limiting

**CR\_0000147093** If rate limiting is applied on the port that connects adjacent OSPF routers, the adjacency is lost after a switch reboot. This issue affects v2 zl modules and 3800 switches.

## sFlow

**CR\_0000147660** In an IPv6-only environment with Stateless Address Autoconfiguration, sFlow incorrectly uses the link-local address as the agent ID.

## SNMP

**CR\_0000131055** The MIB object `hpicfDownloadTftpConfig(1.3.6.1.4.1.11.2.14.11.1.3.5)` in switch software has a value of 1 for enabled and 2 for disabled, but the reverse is actually correct. With this fix the MIB object to enable and disable the TFTP client on the switch is changed to `hpicfDownloadTftpClientConfig(1.3.6.1.4.1.11.2.14.11.1.3.12)`. Also, the integer values are corrected so 1 is disabled and 2 is enabled.

**CR\_0000146616** OSPFv3 traps are not sent by the switch.

**CR\_0000149657** When using the `createAndWait` mode to set parameters via SNMP, multiple RADIUS servers cannot be configured.

**CR\_0000151035** The switch incorrectly reports that MIB object `entPhysicalIsFRU = False` for removable fantrays, power supplies, and transceivers.

**CR\_0000154463** The switch incorrectly reports that MIB object `entPhysicalIsFRU = False` for transceivers for some switches. This improves the original SNMP fix (CR\_0000151035).

## Stacking

**CR\_0000154380** A failover from Commander to Standby with multiple MSTP instances in operation might cause the stack members and connected devices to be unreachable.

## Switch Hang

**CR\_0000153460** Issuing the `boot system` command while VRRP traffic is being received by the switch might cause the switch to hang and not boot completely.

**CR\_0000154152** If the switch is sending output to the console at the time the switch is rebooted, the switch might hang and not boot properly.

## Switch Initialization

**CR\_0000149065** When the switch is rebooted, one module takes about 10 seconds longer to come online than the other modules.

## Transceivers

**CR\_0000146528** After rebooting the switch, the configuration parameter `speed-duplex auto-100` (for a J8177C gigabit-copper transceiver slot) is removed from the config file.

## Web Management

**CR\_0000149099** When Spanning Tree Protocol (STP) is enabled via the Web user interface, "mstp" is shown as the default STP mode, and "mstp" is displayed as the operational mode after the user enables STP and saves the change. However, the command line interface shows that the switch operates in "rpvst" mode.

**Workaround:** From the Web user interface, use the dropdown menu to explicitly select "mstp" from the dropdown options, then save the change.

**CR\_0000149777** After a failover to the Standby Management Module (SMM) or the stack's standby switch, the Web user interface is not accessible via the Out of Band Management (OOBM) port.

## Issues and workarounds

### Certificate Manager

**CR\_0000172987** No warning or action confirmation message is provided at CLI while replacing CSR with a self-signed certificate.

### PoE

**CR\_0000177617** Some vendor powered devices (PDs) supporting the POE+ standard can issue non-standard POE+ packets or packets with invalid TLVs while negotiating for power from the switch (PSE). Strict interpretation of the standard forces power to be cut off to such devices and could cause the PD to reboot continuously.

**Workaround:** Configure the associated port to be `poe-allocated-by value` and `poe-value <required-watts>` on the switch to avoid reboot.

## Upgrade information

### Upgrading restrictions and guidelines

KB.15.16.0012m uses BootROM KB.15.01.0001. If your switch has an older version of BootROM, the BootROM will be updated with this version of software.

For more information about BootROM, see the *HP Switch Software Management and Configuration Guide* for your switch.

- 
- ① **IMPORTANT:** During the software update, the switch will automatically boot twice. The switch will update the primary BootROM, then reboot, and then update the secondary BootROM. After the switch flash memory is updated and the final boot is initiated, no additional user intervention is needed. Do not interrupt power to the switch during this important update.
-

# Support and other resources

## Accessing Hewlett Packard Enterprise Support

- For live assistance, go to the Contact Hewlett Packard Enterprise Worldwide website:  
[www.hpe.com/assistance](http://www.hpe.com/assistance)
- To access documentation and support services, go to the Hewlett Packard Enterprise Support Center website:  
[www.hpe.com/support/hpesc](http://www.hpe.com/support/hpesc)

### Information to collect

- Technical support registration number (if applicable)
- Product name, model or version, and serial number
- Operating system name and version
- Firmware version
- Error messages
- Product-specific reports and logs
- Add-on products or components
- Third-party products or components

## Accessing updates

- Some software products provide a mechanism for accessing software updates through the product interface. Review your product documentation to identify the recommended software update method.
- To download product updates, go to either of the following:
  - Hewlett Packard Enterprise Support Center **Get connected with updates** page:  
[www.hpe.com/support/e-updates](http://www.hpe.com/support/e-updates)
  - Software Depot website:  
[www.hpe.com/support/softwaredepot](http://www.hpe.com/support/softwaredepot)
- To view and update your entitlements, and to link your contracts and warranties with your profile, go to the Hewlett Packard Enterprise Support Center **More Information on Access to Support Materials** page:  
[www.hpe.com/support/AccessToSupportMaterials](http://www.hpe.com/support/AccessToSupportMaterials)

① **IMPORTANT:** Access to some updates might require product entitlement when accessed through the Hewlett Packard Enterprise Support Center. You must have an HP Passport set up with relevant entitlements.

---

## Hewlett Packard Enterprise security policy

A Security Bulletin is the first published notification of security vulnerabilities and is the only communication vehicle for security vulnerabilities.

- Fixes for security vulnerabilities are not documented in manuals, release notes, or other forms of product documentation.
- A Security Bulletin is released when all vulnerable products still in support life have publicly available images that contain the fix for the security vulnerability.

To find security bulletins:

1. Go to the HP Support Center - Hewlett Packard Enterprise at [www.hpe.com/support/hpesc](http://www.hpe.com/support/hpesc).
2. Enter your product name or number and click **Go**.
3. Select your product from the list of results.
4. Click the **Top issues & solutions** tab.
5. Click the **Advisories, bulletins & notices** link.

To initiate a subscription to receive future Hewlett Packard Enterprise Security Bulletin alerts via email, sign up at:

[www4.hpe.com/signup\\_alerts](http://www4.hpe.com/signup_alerts)

## Documents

To find related documents, see Hewlett Packard Enterprise Support Center website:

[www.hpe.com/support/hpesc](http://www.hpe.com/support/hpesc)

Enter your product name or number and click **Go**. If necessary, select your product from the resulting list.

### Related documents

The following documents provide related information:

- *HP Switch Software Access Security Guide K/KA/KB.15.16*
- *HP Switch Software Advanced Traffic Management Guide K/KA/KB.15.16*
- *HP Switch Software Basic Operation Guide*
- *HP Switch Software Feature and Commands Index*
- *HP Switch Software IPv6 Configuration Guide K/KA/KB.15.16*
- *HP Switch Software Management and Configuration Guide K/KA/KB.15.16*
- *HP Switch Software Multicast and Routing Guide K/KA/KB.15.16*
- *Premium License Installation Guide K/KA/KB.15.16*
- *HP OpenFlow 1.3 Administrator Guide K/KA/KB/WB.15.16*
- *HP Service Insertion Guide K/KA/KB/WB.15.16*

## Websites

| Website   | Link   |
|---|--|
| <b>Networking websites</b>                                |  |
| Hewlett Packard Enterprise Networking Information Library | <a href="http://www.hpe.com/networking/resourcefinder">www.hpe.com/networking/resourcefinder</a> |
| Hewlett Packard Enterprise Networking website             | <a href="http://www.hpe.com/info/networking">www.hpe.com/info/networking</a>                     |
| Hewlett Packard Enterprise Networking My Support          | <a href="http://www.hpe.com/networking/support">www.hpe.com/networking/support</a>               |

| Website  | Link   |
|--|--|
| <b>General websites</b>                                |  |
| Hewlett Packard Enterprise Information Library         | <a href="http://www.hpe.com/info/enterprise/docs">www.hpe.com/info/enterprise/docs</a>                     |
| Hewlett Packard Enterprise Support Center              | <a href="http://www.hpe.com/support/hpesc">www.hpe.com/support/hpesc</a>                                   |
| Contact Hewlett Packard Enterprise Worldwide           | <a href="http://www.hpe.com/assistance">www.hpe.com/assistance</a>   |
| Subscription Service/Support Alerts                    | <a href="http://www.hpe.com/support/e-updates">www.hpe.com/support/e-updates</a>                           |
| Software Depot   | <a href="http://www.hpe.com/support/softwaredepot">www.hpe.com/support/softwaredepot</a>                   |
| Customer Self Repair (not applicable to all devices)   | <a href="http://www.hpe.com/support/selfrepair">www.hpe.com/support/selfrepair</a>                         |
| Insight Remote Support (not applicable to all devices) | <a href="http://www.hpe.com/info/insightremotesupport/docs">www.hpe.com/info/insightremotesupport/docs</a> |

## Customer self repair

Hewlett Packard Enterprise customer self repair (CSR) programs allow you to repair your product. If a CSR part needs to be replaced, it will be shipped directly to you so that you can install it at your convenience. Some parts do not qualify for CSR. Your Hewlett Packard Enterprise authorized service provider will determine whether a repair can be accomplished by CSR.

For more information about CSR, contact your local service provider or go to the CSR website: [www.hpe.com/support/selfrepair](http://www.hpe.com/support/selfrepair)

## Remote support

Remote support is available with supported devices as part of your warranty or contractual support agreement. It provides intelligent event diagnosis, and automatic, secure submission of hardware event notifications to Hewlett Packard Enterprise, which will initiate a fast and accurate resolution based on your product's service level. Hewlett Packard Enterprise strongly recommends that you register your device for remote support.

For more information and device support details, go to the following website: [www.hpe.com/info/insightremotesupport/docs](http://www.hpe.com/info/insightremotesupport/docs)

## Documentation feedback

Hewlett Packard Enterprise is committed to providing documentation that meets your needs. To help us improve the documentation, send any errors, suggestions, or comments to Documentation Feedback ([docsfeedback@hpe.com](mailto:docsfeedback@hpe.com)). When submitting your feedback, include the document title, part number, edition, and publication date located on the front cover of the document. For online help content, include the product name, product version, help edition, and publication date located on the legal notices page.