3Com® Baseline Switch 2250-SFP Plus Release Notes

Software Version 02.00.00.01
Part Number: 10016588
Published Date: January 2008

1. Introduction

1.1 *Scope*

These release notes summarize the operational requirements and known issues for the following 3Com Baseline Switch 2250-PWR Plus software release.

Software Release Filename	Description
bm402_00_00_01	Operational Software Baseline Switch 2250-SFP Plus Model # 3C16476CS

1.2 *Online Resources*

To obtain a copy of the *3Com Baseline Switch 2250-SFP Plus User Guide*, visit the 3Com Web site: **www.3Com.com** where you can find the most up-to-date version.

To obtain the latest technical information for your Switch, including a list of known problems and solutions, visit the 3Com Knowledgebase: **http://knowledgebase.3Com.com**

To obtain current software updates (maintenance releases) and associated release notes for the 3Com Baseline Switch 2250-SFP Plus and other 3Com products, visit the 3Com Web site: **www.3Com.com**

2. Known Issues for Release v02.00.00.01

2.1 *802.1X SNMP Authentication Traps*

SNMP traps that should be sent by the switch on the outcome of 802.1X authentication events are not transmitted. However, the 802.1X authentication process functions correctly, and the web interface correctly reflects the status of the authentication.

2.2 *Cable Diagnostics*

Cable diagnostics do not work on the Gigabit ports.

3. Issues Resolved in Release v02.00.00.01

3.1 *Auto Logout of Web Interface*

To improve user security, in this release of code the user interface will time out after approx. 10 mins. of no activity.

3.2 *Support for 3Com Detect Tool*

This release of code now supports the new 3Com Detect tool in addition to the 3Com Switch Discovery application.

3.3 *Traffic Statistics*

In this release of code it is now possible to reset the traffic statistics/counters to zero.

4. Upgrading Software

For instructions on how to upgrade the Switch to this firmware version, please refer to the 3Com Baseline Switch 2250-SFP Plus User Guide (part number 10015240-BA).

5. Additional Information

5.1 *Downgrading to Previous Versions of Operating Software*

Due to minor changes to the internal design of your switch, newer versions of the switch cannot be reprogrammed with versions of operational software prior to this release (v02.00.00.01).

You can see what version of hardware you have by viewing the "Hardware Revision" information on the Summary page of the web interface. If you have a switch with a hardware version of "rv1.0" or later, it cannot run on code released prior to this version. Attempts to load earlier releases will result in a "Data Invalid" message being displayed during the upgrade process.

Switches with a Hardware Revision of "R01" can use any released software.

5.2 *Backing up Configuration Files*

Please note that it is recommended that you back up your configuration before upgrading your switch.