

GigEther-01 (igelan) Gigabit Ethernet Driver for HP-UX 11i v2 of September 2008

Release Notes

GigEther-01 Software Version B.11.23.0809



Legal Notices

© Copyright 2008 Hewlett-Packard Development Company, L.P.

Confidential computer software. Valid license from HP required for possession, use or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing here should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

Table of Contents

1 GigEther-01 (igelan) Gigabit Ethernet Driver for HP-UX 11i v2 of September 2008 Release Notes.....	5
What Is In this Version.....	5
Related Document.....	5

1 GigEther-01 (igelan) Gigabit Ethernet Driver for HP-UX 11i v2 of September 2008 Release Notes

This document discusses the most recent product information pertaining to GigEther-01 (igelan) Gigabit Ethernet Driver for the HP-UX 11i v2 September 2008 release.

This document addresses the following topics:

- “What Is In this Version” (page 5)
- “Related Document” (page 5)

What Is In this Version

The following information describes the updates to the HP-UX-based Gigabit Ethernet driver called `igelan`. The `GigEther-01` software bundle, which is loaded into the operating environment (OE), contains the `igelan` driver.

The September 2008 version of the HP-UX 11i v2 `GigEther-01` driver contains the following fixes:

- | | |
|----------------|--|
| QXCR1000591671 | Support for 1000FD speed on IGELAN. |
| QXCR1000736612 | Fix provided for NIC LED issue on BL860C and BL870C. |

Related Document

For certain known command differences when `igelan` is used on the HP BL860c or BL870c Server Blades, see *HP-UX 11i v2 Network Command Differences when used with HP BL860c/BL870c Server Blades*.

For complete information on what is new or changed in GigEther-01 (igelan) for the HP-UX 11i v2 operating system, see the “I/O Subsystem” subsection of the *HP-UX 11i Version 2 Release Notes* at <http://www.docs.hp.com>.